Line Balancing...

Lecture 40

Purpose is to minimize the number of people and/or machines on an assembly line that is required to produce a given number of units

Line Balancing Example

EXAMPLE-1

Green Grass's plant manager just received marketing's latest forecasts of fertilizer spreader sales for the next year. She wants its production line to be designed to make 2,400 spreaders per week. The plant will operate 40 hours per week.

a. What should be the line's cycle time or throughput rate per hour be?

Throughput rate/hr = 2400 / 40 = 60 spreaders/hr

Cycle Time = 1/Throughput rate= 1/60 = 1 minute = 60 seconds

Line balancing Example continued:

Assume that in order to produce the new fertilizer spreader on the assembly line requires doing the following steps in the order specified:

Work Element	Description	Time (sec)	Immediate Predecessor(s)
Α	Bolt leg frame to hopper	40	None
В	Insert impeller shaft	30	Α
С	Attach axle	50	Α
D	Attach agitator	40	В
E	Attach drive wheel	6	В
F	Attach free wheel	25	С
G	Mount lower post	15	С
н	Attach controls	20	D, E
ı	Mount nameplate	18	F, G
		Total 244	

b. What is the total number of stations or machines required?


TM (total machines) = total production time / cycle time = 244/60 = 4.067 or 5

Draw a Precedence Diagram

SOLUTION

The figure shows the complete diagram. We begin with work element A, which has no immediate predecessors. Next, we add elements B and C, for which element A is the only immediate predecessor. After entering time standards and arrows showing precedence, we add elements D and E,

and so on. The diagram simplifies interpretation. Work element F, for example, can be done anywhere on the line after element C is completed. However, element I must await completion of elements F and G.



Precedence Diagram for Assembling the Big Broadcaster

Allocating work or activities to stations or machines

- The goal is to cluster the work elements into workstations so that
 - 1. The number of workstations required is minimized
 - 2. The precedence and cycle-time requirements are not violated
- The work content for each station is equal (or nearly so, but less than) the cycle time for the line
- Trial-and-error can be used but commercial software packages are also available

Finding a Solution

 The minimum number of workstations is 5 and the cycle time is 60 seconds, so Figure 5 represents an optimal solution to the problem

Station	Candidatis	Choice Time of work-element	Cycle-tim Lift
. SI S2	А В, С	A 7 50 50	60-40=20 60-50=10
S'3	B, G, F D, E, G, F	B 25	60-30=30 30-25=5
S 4	D, E, a E, a	D 40 mil	20-15=5
\$ 5	E, I E H	I 6 E 20	60-18=42 42-6=36 36-20=16

Calculating Line Efficiency

c. Now calculate the efficiency measures of a five-station solution:

Efficiency =
$$\frac{\Sigma t}{nc}$$
(100) = $\frac{244}{5(60)}$ = 81.3%

Balance delay (%) = 100 - Efficiency = 100% - 81.3% = 18.7%

Idle time =
$$nc - \Sigma t = 5(60) - 244 = 56$$
 seconds

A Line Process

- The desired output rate is matched to the staffing or production plan
- Line Cycle Time is the maximum time allowed for work at each station is

$$c = \frac{1}{r}$$

where

c =cycle time in hours

r = desired output rate

A Line Process

 The theoretical minimum number of stations is

$$TM = \frac{\Sigma t}{c}$$

where

 Σt = total time required to assemble each unit

A Line Process

Idle time, efficiency, and balance delay

Idle time =
$$nc - \Sigma t$$

where

n = number of stations

Efficiency (%) =
$$\frac{\sum t}{nc}$$
 (100)

Balance delay (%) = 100 – Efficiency

A company is setting up an assembly line to produce 192 units per 8-hour shift. The following table identifies the work elements, times, and immediate predecessors:

Work Element	Time (sec)	Immediate Predecessor(s)
Α	40	None
В	80	Α
С	30	D, E, F
D	25	В
E	20	В
F	15	В
G	120	Α
н	145	G
ı	130	Н
J	115	C, I
	Total 720	

- a. What is the desired cycle time (in seconds)?
- b. What is the theoretical minimum number of stations?
- c. Use trial and error to work out a solution, and show your solution on a precedence diagram.
- d. What are the efficiency and balance delay of the solution found?

SOLUTION

a. Substituting in the cycle-time formula, we get


$$c = \frac{1}{r} = \frac{8 \text{ hours}}{192 \text{ units}} (3,600 \text{ sec/hr}) = 150 \text{ sec/unit}$$

b. The sum of the work-element times is 720 seconds, so

$$TM = \frac{\Sigma t}{c} = \frac{720 \text{ sec/unit}}{150 \text{ sec/unit-station}} = 4.8 \text{ or 5 stations}$$

which may not be achievable.

c. The precedence diagram is shown in Figure 7.6. Each row in the following table shows work elements assigned to each of the five workstations in the proposed solution.



Work Element	Immediate Predecessor(s)		
Α	None		
В	Α		
С	D, E, F		
D	В		
E	В		
F	В		
G	Α		
Н	G		
1	Н		
J	C, I		

Figure 7.6 – Precedence Diagram

Station	Candidate(s)	Choice	Work-Element Time (sec)	Cumulative Time (sec)	Idle Time (c= 150 sec)
S1					
S2					
S3					
S4					
S5					

Station	Candidate(s)	Choice	Work-Element Time (sec)	Cumulative Time (sec)	Idle Time (c= 150 sec)
S1	Α	A	40	40	110
	В	В	80	120	30
	D, E, F	D	25	145	5
S2	E, F, G	G	120	120	30
	E, F	E	20	140	10
S3	F, H	H	145	145	5
S4	F, I		130	130	20
	F	F	15	145	5
S5	С	C	30	30	120
	J	U	115	145	5

d. Calculating the efficiency, we get

Efficiency (%) =
$$\frac{\Sigma t}{nc}$$
 (100) = $\frac{720 \text{ sec/unit}}{5(150 \text{ sec/unit})}$
= 96%

Thus, the balance delay is only 4 percent (100–96).