


### Sensing and Estimation in Robotics


### Assignment 3


### 1. Distance only measurements





















Zoomed in error ellipse





### 2. Bearing only measurement





















### Zoomed in Error Ellipse





### 3. Distance and Bearing Measurement




















Error Ellipse (Zoomed In)





Extra Credit


Bearing only measurement with one landmark.

















Error Ellipse – Zoomed In

