

The starboard generator high-temp alarm.

Three times in eighteen months.

Three different chiefs. Three first-time diagnoses.

Each one began the same path. Each one rediscovered the heat exchanger.

Two days of external technician time.
Again.

€950 per day. €1,900 per recurrence.

The fix was in the system the whole time.

Same fault to the equipment. Three separate faults to the system.

This alarm has occurred before.

• Fault History · Stbd generator high-temp		2 MATCHED
2024-03 · CE M	Heat exchanger fouled · resolved	
2023-09 · CE R	Heat exchanger fouled · resolved	
Fix on record		WO-2188 →
Part used both times		PL-1104

The third chief reads what the first chief found.

• Cross-Domain Chain	LINKED
Fault Report	FR-0847 →
Work Order	WO-3291 →
Parts List	PL-1104 →
Purchase Order	PO-0582 →
Receiving	CONFIRMED

The diagnostic path is not walked twice.

Control over your complexity.

celeste7.ai