

The port watermaker is degrading.

TDS readings slipping. Recovery rate down 12% in six weeks.

You log the symptom. The PMS shows
the equipment record.

You move on.

Three weeks later you order the wrong membrane.

Wrong size. Lead time eleven days. Charter starts in five.

The right membrane was on the shelf
the entire time.

Bought during the last refit. Logged against a different equipment record.

You did not need to remember it. The system knows.

Fault logged: TDS rising.

• Inventory Match		IN STOCK
Part	BFM-■■■■-V8R	
On board	2 units	
Location	Stbd lazarette · bin 6	
Last delivered	2024-02-14	
Linked fault	FR-0847 →	

One click. Pre-populated work order.
Inventory deducted. Handover
updated.

• Cross-Domain Chain	LINKED
Fault Report	FR-0847 →
Work Order	WO-3291 →
Parts List	PL-1104 →
Purchase Order	PO-0582 →
Receiving	CONFIRMED

The system that connects the dots.

Control over your complexity.

celeste7.ai