

The yard delivered the drawing in 2018.

Stamped. Signed. The most authoritative document on the vessel.

Six refits later, the drawing is a fiction.

The wiring changed. The valve was rerouted. The starboard pump was moved port. None of it went back to the yard.

The next refit begins with a drawing that no longer matches the vessel.

The yard quotes from fiction. The crew corrects in person. The cost is the correction.

The drawing is still the most
authoritative document. That is the
problem.

The drawing did not change. The vessel did. Nothing tracked the gap.

Drawing + modifications + change history.

• Cross-Domain Chain	LINKED
Fault Report	FR-0847 →
Work Order	WO-3291 →
Parts List	PL-1104 →
Purchase Order	PO-0582 →
Receiving	CONFIRMED

The vessel in 2018. The vessel today.
Both signed.

• Cross-Domain Chain	LINKED
Fault Report	FR-0847 →
Work Order	WO-3291 →
Parts List	PL-1104 →
Purchase Order	PO-0582 →
Receiving	CONFIRMED

The refit begins from reality, not from 2018.

Control over your complexity.

celeste7.ai