

The handover that *wasn't* there.

A chief joins a vessel mid-season. The previous chief is gone. There was no overlap.

The handover doc is a Word file on a shared drive.

Multiple authors. Different fonts. Different colours. Updated through the rotation, finalised the night before the outgoing engineer flies home.

Written under pressure, by tired people, the night before a flight.

Faults marked investigating without signature. Captain requests logged in red without context. Supplier names added without numbers. The record is colour-coded improvisation.

"The engineers spend three days every rotation rebuilding what the last team knew."

Three days × six rotations a year. Weeks of working life, every year, spent reconstructing the rotation they missed.

A decade of PMS releases. The handover doc opens the same way it did when it started.

The problem has been named for years. The industry has learned to live with it. Until now.

The handover, but every line is a link.

• Cross-Domain Chain	LINKED
Fault Report	FR-0847 →
Work Order	WO-3291 →
Parts List	PL-1104 →
Purchase Order	PO-0582 →
Receiving	CONFIRMED

Compiled. Signed. Ready when the relief opens his laptop.

• Handover Document	SIGNED
Outgoing CE → Incoming CE	
Sections complete	12 / 12
Captain countersigned	VERIFIED
Audit trail	47 signed events →

Eight months of operational context.

Not two days of verbal briefing.

TECHNICAL HANDOVER REPORT

M/Y Test Vessel

DOCUMENT NO.

THR-0042

GENERATED

24 Mar 2026, 16:15 UTC

PERIOD

20/03/2025 - 24/03/2026

Control over your complexity.

The handover that wasn't there. Now it is.

celeste7.ai

ENGINEERING

1 item

THE HANDOVER THAT WASN'T THERE

09 / 09

1. High Coolant Temperature on Starboard Engine

You need to address the high coolant temperature reading on the starboard engine. Await inspection parts from the Cat dealer.