

## Survey of the Tower of London

A survey of the fabric and furnishings of the Tower of London.

The roof of the great hall wants attention before winter. The kitchens are sound. The moat requires dredging.

Estimated cost of necessary works appended.

| Works    | Estimate (£) |
|----------|--------------|
| Roof     | 120          |
| Drainage | 60           |
| Glazing  | 45           |