-



Oakenhurst Aircraft Services Ltd Claydons Lane Rayleigh Essex SS6 7UP United Kingdom Tel: +44 (0)1268741622

EASA Part 145: EASA.UK.145.00524

FAR 145:

Workshop Report

No: IR17561

Issue: 02

Date: 02-Jun-22

Ukraine International Airlines

State International Airport Boryspol

Boryspil-7

Hora

Ukraine

08307

Ukraine

Attn: Mr Dmitriy Shapovalov

Tel: +380445937601

Fax:

E-Mail: uiatechorders@flyuia.com

Your Ref: R0027522

Our Ref No: WPU17559

Test Required: N/A

Part No: 15800-358

Description: Valve Assy

TSN: N/A

CSN: N/A

Serial No: 28077

Workscope: E&E Repair

TSO: N/A

CSO: N/A

DoM:

Overhauled:

Inspected:

Removed From:

Serial No:

Reg No: UR-PSX

Position:

Technical Reference: LIB03471 - Issue No: N/A - Rev No: 5

Inspection Findings:

UNIT RECEIVED IN AVERAGE CONDITION. DEFECT CONFIRMED.UNIT DIDN'T PASS INTERNAL LEAKAGE PRESSURE TEST. DISASSEMBLED THE UNIT FOR TROUBLESHOOTING AND REPAIR. DURING TROUBLESHOOTING LIMESCALE DELAMINATION OVER ALL PARTS WERE FOUND, ALSO O-RING AND POPPET HAS BAD CONDITION. ALL PARTS DEEPLY CLEANED. O-RINGG AND POPPET WERE REPLACED. UNIT WAS REASSEMBLED, REPAIRED, CLEANED, TESTED AND RELEASED TO SERVICE.

Signed:

For and on the behalf of Oakenhurst Aircraft Services Ltd

Name:

Date: 02/06/22

TBA