4. Organization Name and Address: Approving Civil Aviation 9960 NW 116 WAY SUITE 10 Miami, FL. 33178 Illuminair Support Corp. 12. Remarks: **I6UR977X FAA/United States** Replaced all defective parts listed on progressive findings. Unit was repaired and tested IAW Eaton CMM ATA 29-09-04 Rev.# 5 Dated December 30, 2016 **Hyd Pressure Switch** Description: 2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG Part Number: 211C223-516 9. Quantity: 10. Serial Number: J005445A Work Order/Contract/Invoice Number: 3. Form Tracking Number: Ξ Status/Work: REPAIRED 210424 210424

13a Certifies the items identified above were manufactured in conformity to: 13d. Name (Typed or Printed): 13b.Authorized Signature: N/A Approved design data and are in a condition for safe operation. Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work, the article is considered ready for release to service under EASA Part 145 approval No. [EASA 145.6154] Non-approved design data specified in Block 12 13e. Date (dd/mmm/yyyy) 13c. Approval/Authorization No.: User/Installer Responsibilities 14b. Authorized Signature: 14a. X 14 CFR 43.9 Return to Service Antonio Barzaga 14d. Name (Typed or Printed): and described in Block 12 was accomplished in accordance with Title 14, Code of Certifies that unless otherwise specified in Block 12, the work identified in Block 11 Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. Other regulation specified in Block 12 14e. Date (dd/mmm/yyyy): 14c. Approval/Certificate No.: 29/Apr/2021 **I6UR977X**

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft article.

the user/installer ensures that his/her airworthiness authority accepts aircraft article(s) from the airworthiness authority of the country specified in Block 1. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that

regulations by the user/installer before the aircraft may be flown. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national

FAA Form 8130-3 (02-14) NSN: 0052-00-012-9005 Illuminair Support Corp. 9960 NW 116 WAY SUITE 10

Miami, FL. 33178

Phone: (305) 884-2882 Fax: (305) 884-5159

E-Mail: sales@illuminairsupport.com

FAA #: I6UR977X

Work Order #: 210424
Work Order Date: 03/03/2021

| Cust#: 753 | RO#: FTR6016260 | Sh | op #: 7 Core Return?: | | | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------|---------------------------------|-----------------------------------|----------------------------------------------------|--|--|
| Desc: Hyd Pressure Switch | S/N: <u>J005445A</u> | MFG: Eator | ATA: 29-09-04 | | | |
| P/N: 211C223-516 | Model #: <u>S271T452-3</u> | Rev. Date: | <u>12/30/2016</u> Rev #: <u>5</u> | | | |
| FAA\EASA AD Notes applicable: Unit | t is not affected by any EASA | & FAA AD's. | | | | |
| Work Req: Repair | Trouble Reported: Signal not in limit. | | | | | |
| Rec Inspection: Unit received externally | | | | | | |
| Special Instructions: No special instructions requested. | | | | | | |
| | Inspector: <u>Antonio Barzaga</u> | | Date: <u>3/3/2021</u> | | | |
| Preliminary Inspection: | | | | | | |
| Visual P/N and S/N verified. Inspection: | | | | | | |
| Hidden Verified?: Yes: ☐ No: ☑ Damage: | 2 | | | | | |
| Tech: <u>Jairo Mejia</u> | Inspector: An | onio Barzaga | | Date: <u>3/5/2021</u> | | |
| Testing: Trouble Verified?: Yes: | ✓ No: ☐ Bench Cho | eck?: Passe | d 🗌 Failed | . ✓ | | |
| Unit failed functional test. Micro | oswitch defective. | | | | | |
| | | to de Damas | | Date: 3/9/2021 | | |
| Tech: Eduardo Gonzalez | Inspector: An | tonio Barzaga | arzaga Date. <u>5/8/202</u> | | | |
| | In Process In | 8 | | | | |
| Progressive External inspection reveals requires replacement. All dispersions reveals requires. Repair quote. | s unit dirty and greasy. Internal in lefective parts must be replaced. | spection revea Unit needs to | als Microswitch be refurbished | defective. Disturbed O-ring before goes back to | | |
| Tech: <u>Jairo Mejia</u> | Inspector: <u>An</u> | tonio Barzaga | | Date: <u>3/10/2021</u> | | |
| Corrective Replaced all defective parts listed on progressive findings. Unit was repaired and tested IAW Eaton CMM ATA 29-09-Action: O4 Rev.# 5 Dated December 30, 2016. | | | | | | |
| Tech: Rolando Lugo | Inspector: <u>Ja</u> | iro Mejia | | Date: 4/29/2021 | | |
| | | | | | | |

Illuminair Support Corp. 9960 NW 116 WAY SUITE 10

Miami, FL. 33178

Phone: (305) 884-2882 Fax: (305) 884-5159

E-Mail: sales@illuminairsupport.com

FAA #: I6UR977X

Work Order #: 210424 Work Order Date: 03/03/2021

Parts Used:

| P/N: | Description: | Qty: | Cond: | PO#: |
|---------------------|---------------------|------|-------|---------|
| JPM182 | Switch | 1 | NE | 7210723 |
| JYK121 | O-Ring | 1 | NE | 7210723 |
| Standard Materials. | Standard Materials. | 1 | | |

Final Inspection

Bench Check?: Yes: ✓ No:

Work Performed: Repaired

AD Notes\SB's: Unit is not currently affected by any EASA & FAA AD's.

Date: 04/29/2021

Technician: Rolando Lugo

Inspector: Antonio Barzaga

The appliance\component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration, is approved for return to service and is certified as airworthy.

Auth. Signature:



Illuminair Support Corp. I6UR977X

9960 NW 116 WAY SUITE 10

Miami, FL. 33178

Phone: (305) 884-2882 Fax: (305) 884-5159

E-Mail: sales@illuminairsupport.com

SHIPPER #: 30727

Shipping Ticket

Bill To:

FL Technics Rodunios Road 18 Vilnius,LT 02188-Lithuania

Shipped To:

FL Technics C/O JSC Vliniaus Tranzitas Jurgio Dobkeviciaus Str. 7 Building 7 Vilnius,LT 02189-Lithuania

Terms: Net 30 Days

F.O.B.: Miami

Order Date: 03/03/2021

RO#: FTR6016260

..

Approved by: Nerijus Grinkevičius ShipVia: DHL Express

5...p v.u. 2...2 = xp. 000

Work Order #: 210424

Customer #: 753

ShipVia Notes: 956010616

Default Account: 956010616

 P/N:
 Model #:
 Description:
 Mfg:
 S/N:
 Cond:

 211C223-516
 S271T452-3
 Hyd Pressure Switch
 Eaton
 J005445A
 REPAIRED

From:

Illuminair Support Corp.

9960 NW 116 WAY SUITE 10

Miami, FL. 33178

To: Attn: Nerijus Grinkevičiu PO\RO#: FTR6016260

FL Technics

C/O JSC Vliniaus Tranzitas Jurgio Dobkeviciaus Str. 7

Building 7

Vilnius, LT 02189-

Lithuania

| Print Name: | |
|--------------|--|
| | |
| Received by: | |

Date: