

# AutoSentinel

## Unauthorized Construction Detection Report

Generated: 02 August 2026, 14:49 IST | Analysis period: 2019–2026  
Area analysed: Custom scanned area (19.4237, 72.7740) to (19.4293, 72.7817)

Severity: LOW | Risk Score: 10.7/100

### Zone Details

| Field                       | Value                                                          |
|-----------------------------|----------------------------------------------------------------|
| Zone ID                     | live a5be1a41 2                                                |
| Coordinates                 | 19.426607°N, 72.779663°E                                       |
| Constructed Area            | 0.06 hectares (600 sq metres)                                  |
| Severity Level              | LOW                                                            |
| Risk Score                  | 10.7 / 100                                                     |
| Violation Type              | POSSIBLE PERMIT VIOLATION                                      |
| Bhuvan Land Classification  | Forest fringe                                                  |
| Bhuvan Overlap / Confidence | 84.4% / Low                                                    |
| Bhuvan Data Source          | No land-use polygon intersected                                |
| OSM Overlays                | FOREST ENCROACHMENT, CONSTRUCTION ACTIVITY, ROAD BUFFER REVIEW |
| Legal Flags                 | FOREST ENCROACHMENT, CONSTRUCTION ACTIVITY, ROAD BUFFER REVIEW |
| Risk Boost                  | 26.5                                                           |

### Bhuvan Land-use Verification

The zone was checked against the available ISRO Bhuvan-compatible land-use layer. Dominant classification: **Forest fringe**; polygon overlap: **84.4%**; confidence: **Low**. Source: No land-use polygon intersected.

### How the Risk Score Was Calculated

| Scoring Factor        | Value                     | Contribution                           |
|-----------------------|---------------------------|----------------------------------------|
| Construction Area     | 0.06 ha                   | Primary driver - larger = higher score |
| Land Classification   | POSSIBLE PERMIT VIOLATION | Determines violation severity          |
| NDBI Change Magnitude | > 0.15 threshold          | Confirms built-up area increase        |
| Time Period           | 2019 → 2026               | Change detection window                |
| Final Score           | 10.7/100                  | Severity: LOW                          |

This zone received a LOW score of 10.7/100 because the detected construction covers 600 sq metres - a small satellite-detected built-up change.

Land Classification Note: The detected change requires a land-use and permit review against available zoning data. Ground inspection is required to determine the applicable land use rules.

---

## Satellite Evidence

The images below show the flagged location in 2019 (before) and 2026 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2019 - Before Construction



2026 - After Construction

---

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.