

Severity: LOW | Risk Score: 10.0/100

Zone Details

Field	Value
Zone ID	live_35cccf72_0
Coordinates	19.427910°N, 72.786939°E
Constructed Area	0.05 hectares (500 sq metres)
Severity Level	LOW
Risk Score	10.0 / 100
Violation Type	UNVERIFIED ZONE
Bhuvan Land Classification	Forest fringe
Bhuvan Overlap / Confidence	67.4% / 88%
Bhuvan Data Source	ISRO Bhuvan LULC mock verification
OSM Overlays	FOREST_ENCROACHMENT, CONSTRUCTION_ACTIVITY, ROAD_BUFFER_REVIEW
Legal Flags	FOREST_ENCROACHMENT, CONSTRUCTION_ACTIVITY, ROAD_BUFFER_REVIEW
Risk Boost	20.5

Bhuvan Land-use Verification

The zone was checked against the available ISRO Bhuvan-compatible land-use layer. Dominant classification: **Forest fringe**; polygon overlap: **67.4%**; confidence: **88%**. Source: ISRO Bhuvan LULC mock verification.

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	0.05 ha	Primary driver - larger = higher score
Land Classification	UNVERIFIED ZONE	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2024 → 2025	Change detection window
Final Score	10.0/100	Severity: LOW

This zone received a LOW score of 10.0/100 because the detected construction covers 500 sq metres - a small satellite-detected built-up change.

Land Classification Note: The land classification for this zone could not be verified against available zoning data. The flag is based solely on the magnitude of satellite-detected construction change. Ground verification is required to determine the applicable land use rules.

Satellite Evidence

The images below show the flagged location in 2024 (before) and 2025 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2024 - Before Construction



2025 - After Construction

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.