

# AutoSentinel

## Unauthorized Construction Detection Report

Generated: 30 July 2026, 22:03 IST | Analysis period: 2019–2026  
Area analysed: Custom scanned area (19.2645, 72.8260) to (19.3092, 72.8833)

Severity: LOW | Risk Score: 11.3/100

### Zone Details

| Field                       | Value                                                     |
|-----------------------------|-----------------------------------------------------------|
| Zone ID                     | live 4ccfe44e 307                                         |
| Coordinates                 | 19.269857°N, 72.880749°E                                  |
| Constructed Area            | 0.07 hectares (700 sq metres)                             |
| Severity Level              | LOW                                                       |
| Risk Score                  | 11.3 / 100                                                |
| Violation Type              | POSSIBLE PERMIT VIOLATION                                 |
| Bhuvan Land Classification  | Residential                                               |
| Bhuvan Overlap / Confidence | 100.0% / High                                             |
| Bhuvan Data Source          | OpenStreetMap (Overpass, Dahisar extract)                 |
| OSM Overlays                | PROTECTED LAND, CONSTRUCTION ACTIVITY, ROAD BUFFER REVIEW |
| Legal Flags                 | PROTECTED LAND, CONSTRUCTION ACTIVITY, ROAD BUFFER REVIEW |
| Risk Boost                  | 30.5                                                      |

### Bhuvan Land-use Verification

The zone was checked against the available ISRO Bhuvan-compatible land-use layer. Dominant classification: **Residential**; polygon overlap: **100.0%**; confidence: **High**. Source: OpenStreetMap (Overpass, Dahisar extract).

### How the Risk Score Was Calculated

| Scoring Factor        | Value                     | Contribution                           |
|-----------------------|---------------------------|----------------------------------------|
| Construction Area     | 0.07 ha                   | Primary driver - larger = higher score |
| Land Classification   | POSSIBLE PERMIT VIOLATION | Determines violation severity          |
| NDBI Change Magnitude | > 0.15 threshold          | Confirms built-up area increase        |
| Time Period           | 2019 → 2026               | Change detection window                |
| Final Score           | 11.3/100                  | Severity: LOW                          |

This zone received a LOW score of 11.3/100 because the detected construction covers 700 sq metres - a small satellite-detected built-up change.

Land Classification Note: The detected change requires a land-use and permit review against available zoning data. Ground inspection is required to determine the applicable land use rules.

---

## Satellite Evidence

Satellite image crops are not available for this zone. Images are pre-generated for Critical severity zones only. Use the AutoSentinel dashboard to view live satellite thumbnails for this location.

---

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.