

Severity: MEDIUM | Risk Score: 71.0/100

Zone Details

Field	Value
Zone ID	live_69aef926_23
Coordinates	19.263843°N, 72.876300°E
Constructed Area	0.82 hectares (8,200 sq metres)
Severity Level	MEDIUM
Risk Score	71.0 / 100
Violation Type	UNVERIFIED ZONE
Bhuvan Land Classification	Open Land
Bhuvan Overlap / Confidence	95.9% / High
Bhuvan Data Source	OpenStreetMap (Overpass, Dahisar extract)
OSM Overlays	None
Legal Flags	None
Risk Boost	0.0

Bhuvan Land-use Verification

The zone was checked against the available ISRO Bhuvan-compatible land-use layer. Dominant classification: **Open Land**; polygon overlap: **95.9%**; confidence: **High**. Source: OpenStreetMap (Overpass, Dahisar extract).

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	0.82 ha	Primary driver - larger = higher score
Land Classification	UNVERIFIED ZONE	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2024 → 2025	Change detection window
Final Score	71.0/100	Severity: MEDIUM

This zone received a MEDIUM score of 71.0/100 because the detected construction covers 0.82 hectares - between 0.2 and 1 hectare. This is a moderate satellite-detected change requiring human verification.

Land Classification Note: The land classification for this zone could not be verified against available zoning data. The flag is based solely on the magnitude of satellite-detected construction change. Ground verification is required to determine the applicable land use rules.

Satellite Evidence

The images below show the flagged location in 2024 (before) and 2025 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2024 - Before Construction



2025 - After Construction

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.