

■ Severity: LOW | Risk Score: 40.7/100

Zone Details

Field	Value
Zone ID	live_569bf945_4
Coordinates	19.441055°N, 72.863760°E
Constructed Area	0.06 hectares (600 sq metres)
Severity Level	LOW
Risk Score	40.7 / 100
Violation Type	RAILWAY BUFFER VIOLATION
Bhuvan Land Type	unverified
OSM Overlays	RAILWAY_BUFFER_VIOLATION, RIVER_BUFFER_VIOLATION
Legal Flags	RAILWAY_BUFFER_VIOLATION, RIVER_BUFFER_VIOLATION
Risk Boost	30.0

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	0.06 ha	Primary driver - larger = higher score
Land Classification	RAILWAY BUFFER VIOLATION	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2019 → 2023	4-year change window
Final Score	40.7/100	Severity: LOW

This zone received a LOW score of 40.7/100 because the detected construction covers 600 sq metres - a small structure that should be logged for routine inspection.

Land Classification Note: Land classification pending verification.

Legal Analysis: OSM infrastructure overlays detected: RAILWAY BUFFER VIOLATION, RIVER BUFFER VIOLATION. This construction appears to violate: RAILWAY BUFFER VIOLATION, RIVER BUFFER VIOLATION. Risk reason: Railway boost +15; River boost +15. Final risk: 40.7/100.

Satellite Evidence

The images below show the flagged location in 2019 (before) and 2023 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2019 - Before Construction



2023 - After Construction

Recommended Action

Log for routine inspection

1. Log in municipal records for routine inspection cycle.
2. No immediate action required unless escalated by complaint.

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.