

AutoSentinel

Unauthorized Construction Detection Report

Generated: 15 July 2026, 20:01 IST | Area: Custom scanned area (19.2260, 72.8317) to (19.3019, 72.9114) | Analysis Period: 2024-2025

Severity: HIGH | Risk Score: 90.3/100

Zone Details

Field	Value
Zone ID	live_c195d561_29
Coordinates	19.288690°N, 72.837917°E
Constructed Area	1.05 hectares (10,500 sq metres)
Severity Level	HIGH
Risk Score	90.3 / 100
Violation Type	WETLAND ENCROACHMENT
Bhuvan Land Classification	Wetland
Bhuvan Overlap / Confidence	87.5% / High
Bhuvan Data Source	OpenStreetMap (Overpass, Dahisar extract)
OSM Overlays	None
Legal Flags	WETLAND_ENCROACHMENT
Risk Boost	20.0

Bhuvan Land-use Verification

The zone was checked against the available ISRO Bhuvan-compatible land-use layer. Dominant classification: **Wetland**; polygon overlap: **87.5%**; confidence: **High**. Source: OpenStreetMap (Overpass, Dahisar extract).

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	1.05 ha	Primary driver - larger = higher score
Land Classification	WETLAND ENCROACHMENT	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2024 → 2025	Change detection window
Final Score	90.3/100	Severity: HIGH

This zone received a HIGH score of 90.3/100 because the detected construction covers 1.1 hectares - between 1 and 5 hectares. This scale of development on unverified land indicates significant unauthorized construction activity.

Land Classification Note: Land classification pending verification.

Satellite Evidence

The images below show the flagged location in 2024 (before) and 2025 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2024 - Before Construction



2025 - After Construction

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.