

■ Severity: HIGH | Risk Score: 100.0/100

## Zone Details

| Field            | Value                                                                      |
|------------------|----------------------------------------------------------------------------|
| Zone ID          | live_b8d0965d_90                                                           |
| Coordinates      | 19.142616°N, 72.943066°E                                                   |
| Constructed Area | 2.88 hectares (28,800 sq metres)                                           |
| Severity Level   | HIGH                                                                       |
| Risk Score       | 100.0 / 100                                                                |
| Violation Type   | RAILWAY BUFFER VIOLATION                                                   |
| Bhuvan Land Type | unverified                                                                 |
| OSM Overlays     | RAILWAY_BUFFER_VIOLATION, RIVER_BUFFER_VIOLATION, INDUSTRIAL_ZONE_ACTIVITY |
| Legal Flags      | RAILWAY_BUFFER_VIOLATION, RIVER_BUFFER_VIOLATION, INDUSTRIAL_ZONE_ACTIVITY |
| Risk Boost       | 35.0                                                                       |

## How the Risk Score Was Calculated

| Scoring Factor        | Value                    | Contribution                           |
|-----------------------|--------------------------|----------------------------------------|
| Construction Area     | 2.88 ha                  | Primary driver - larger = higher score |
| Land Classification   | RAILWAY BUFFER VIOLATION | Determines violation severity          |
| NDBI Change Magnitude | > 0.15 threshold         | Confirms built-up area increase        |
| Time Period           | 2019 → 2023              | 4-year change window                   |
| Final Score           | 100.0/100                | Severity: HIGH                         |

This zone received a HIGH score of 100.0/100 because the detected construction covers 2.9 hectares - between 1 and 5 hectares. This scale of development on unverified land indicates significant unauthorized construction activity.

Land Classification Note: Land classification pending verification.

Legal Analysis: OSM infrastructure overlays detected: RAILWAY BUFFER VIOLATION, RIVER BUFFER VIOLATION, INDUSTRIAL ZONE ACTIVITY. This construction appears to violate: RAILWAY BUFFER VIOLATION, RIVER BUFFER VIOLATION, INDUSTRIAL ZONE ACTIVITY. Risk reason: Railway boost +15; River boost +15; Industrial boost +5. Final risk: 100.0/100.

## Satellite Evidence

The images below show the flagged location in 2019 (before) and 2023 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2019 - Before Construction



2023 - After Construction

---

## Recommended Action

### Priority inspection within 48 hours

1. Schedule ground inspection within 48 hours.
2. Verify building permit status with local municipal authority.
3. Issue notice to owner if construction is found to be unauthorized.
4. Escalate to CRITICAL if structure is found on protected land.

---

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.