

■ Severity: CRITICAL | Risk Score: 90.2/100

Zone Details

Field	Value
Zone ID	655
Coordinates	19.390497°N, 72.852362°E
Constructed Area	5.18 hectares (51,800 sq metres)
Severity Level	CRITICAL
Risk Score	90.2 / 100
Violation Type	UNVERIFIED ZONE
Bhuvan Land Type	Unverified
OSM Overlays	None
Legal Flags	None
Risk Boost	0.0

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	5.18 ha	Primary driver - larger = higher score
Land Classification	UNVERIFIED ZONE	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2019 → 2023	4-year change window
Final Score	90.2/100	Severity: CRITICAL

This zone received a CRITICAL score of 90.2/100 because the detected construction covers 5.2 hectares - exceeding the 5-hectare threshold that indicates large-scale unauthorized development. Structures of this size cannot be accidental extensions and require immediate enforcement action.

Land Classification Note: The land classification for this zone could not be verified against available zoning data. The flag is based solely on the magnitude of satellite-detected construction change. Ground verification is required to determine the applicable land use rules.

Satellite Evidence

The images below show the flagged location in 2019 (before) and 2023 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2019 - Before Construction



2023 - After Construction

Recommended Action

Immediate ground inspection required — large unauthorized structure detected

1. Dispatch ground inspection team immediately to verify satellite findings.
2. Cross-check location against RERA permit database for registered projects.
3. If no valid permit found, issue Stop Work Notice under MRTP Act Section 52.
4. Initiate demolition proceedings if construction exceeds permissible limits.
5. File case with District Collector if land falls under Forest/Government category.

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.