

Severity: LOW | Risk Score: 12.7/100

Zone Details

Field	Value
Zone ID	live_522f8655_52
Coordinates	19.577210°N, 81.895836°E
Constructed Area	0.09 hectares (900 sq metres)
Severity Level	LOW
Risk Score	12.7 / 100
Violation Type	UNVERIFIED ZONE
Bhuvan Land Classification	Unknown
Bhuvan Overlap / Confidence	70.4% / Low
Bhuvan Data Source	No land-use polygon intersected
OSM Overlays	FOREST_ENCROACHMENT, CONSTRUCTION_ACTIVITY, ROAD_BUFFER_REVIEW
Legal Flags	FOREST_ENCROACHMENT, CONSTRUCTION_ACTIVITY, ROAD_BUFFER_REVIEW
Risk Boost	26.5

Bhuvan Land-use Verification

The zone was checked against the available ISRO Bhuvan-compatible land-use layer. Dominant classification: **Unknown**; polygon overlap: **70.4%**; confidence: **Low**. Source: No land-use polygon intersected.

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	0.09 ha	Primary driver - larger = higher score
Land Classification	UNVERIFIED ZONE	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2024 → 2025	Change detection window
Final Score	12.7/100	Severity: LOW

This zone received a LOW score of 12.7/100 because the detected construction covers 900 sq metres - a small satellite-detected built-up change.

Land Classification Note: The land classification for this zone could not be verified against available zoning data. The flag is based solely on the magnitude of satellite-detected construction change. Ground verification is required to determine the applicable land use rules.

Satellite Evidence

Satellite image crops are not available for this zone. Images are pre-generated for Critical severity zones only. Use the AutoSentinel dashboard to view live satellite thumbnails for this location.

permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.