

Severity: MEDIUM | Risk Score: 76.5/100

Zone Details

Field	Value
Zone ID	53
Coordinates	19.493990°N, 72.803035°E
Constructed Area	0.93 hectares (9,300 sq metres)
Severity Level	MEDIUM
Risk Score	76.5 / 100
Violation Type	FOREST ENCROACHMENT
Bhuvan Land Classification	unverified
Bhuvan Overlap / Confidence	0.0% / Unknown
Bhuvan Data Source	No land-use layer available for this zone
OSM Overlays	None
Legal Flags	None
Risk Boost	0.0

Bhuvan Land-use Verification

The zone was checked against the available ISRO Bhuvan-compatible land-use layer. Dominant classification: **unverified**; polygon overlap: **0.0%**; confidence: **Unknown**. Source: No land-use layer available for this zone.

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	0.93 ha	Primary driver - larger = higher score
Land Classification	FOREST ENCROACHMENT	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2019 → 2023	Change detection window
Final Score	76.5/100	Severity: MEDIUM

This zone received a MEDIUM score of 76.5/100 because the detected construction covers 0.93 hectares - between 0.2 and 1 hectare. This is a moderate satellite-detected change requiring human verification.

Land Classification Note: The construction location falls within an area classified as protected forest or woodland in the available reference overlays. Construction on forest land without Forest Department clearance may be prohibited under the Forest Conservation Act, 1980.

Satellite Evidence

The images below show the flagged location in 2019 (before) and 2023 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2019 - Before Construction



2023 - After Construction

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.