

Severity: CRITICAL | Risk Score: 99.0/100

Zone Details

Field	Value
Zone ID	930
Coordinates	19.352543°N, 72.861890°E
Constructed Area	18.98 hectares (189,802 sq metres)
Severity Level	CRITICAL
Risk Score	99.0 / 100
Violation Type	AGRICULTURAL LAND
Bhuvan Land Classification	unverified
Bhuvan Overlap / Confidence	0.0% / Unknown
Bhuvan Data Source	No land-use layer available for this zone
OSM Overlays	None
Legal Flags	None
Risk Boost	0.0

Bhuvan Land-use Verification

The zone was checked against the available ISRO Bhuvan-compatible land-use layer. Dominant classification: **unverified**; polygon overlap: **0.0%**; confidence: **Unknown**. Source: No land-use layer available for this zone.

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	18.98 ha	Primary driver - larger = higher score
Land Classification	AGRICULTURAL LAND	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2019 → 2023	Change detection window
Final Score	99.0/100	Severity: CRITICAL

This zone received a CRITICAL score of 99.0/100 because the detected construction covers 19.0 hectares - exceeding the 5-hectare threshold that indicates large-scale unauthorized development. Structures of this size cannot be accidental extensions and should be reviewed against local approvals.

Land Classification Note: The construction location falls on land classified as agricultural. Converting agricultural land to non-agricultural use without Maharashtra government permission violates the Maharashtra Land Revenue Code.

Satellite Evidence

The images below show the flagged location in 2019 (before) and 2023 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2019 - Before Construction



2023 - After Construction

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.