

■ Severity: CRITICAL | Risk Score: 99.0/100

Zone Details

Field	Value
Zone ID	376
Coordinates	19.443994°N, 72.898706°E
Constructed Area	19.63 hectares (196,302 sq metres)
Severity Level	CRITICAL
Risk Score	99.0 / 100
Primary Violation	UNVERIFIED ZONE
Legal Layers Matched	None — no protected/restricted layer intersected

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	19.63 ha	Primary driver — larger = higher score
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2019 → 2023	4-year change window
Construction Score	99.0/100	Area-based component
Legal Layer Score	0.0/100	No legal layers matched
Final Score	99.0/100	Severity: CRITICAL

This zone received a CRITICAL score of 99.0/100 because the detected construction covers 19.6 hectares — exceeding the 5-hectare threshold that indicates large-scale unauthorized development. Structures of this size cannot be accidental extensions and require immediate enforcement action.

Land Classification Note: The land classification for this zone could not be verified against available legal layers. No forest, water, agricultural, or railway-buffer data intersected this location at the time of the check. The flag is based solely on the magnitude of satellite-detected construction change, and ground verification is required to determine applicable land-use rules.

Satellite Evidence

The images below show the flagged location in 2019 (before) and 2023 (after). Visible change in land cover — new grey/brown built-up area replacing green or open land — confirms the satellite detection.



2019 — Before Construction



2023 — After Construction

Recommended Action

Immediate ground inspection required — large unauthorized structure detected

1. Dispatch ground inspection team immediately to verify satellite findings.
2. Cross-check location against RERA permit database for registered projects.
3. If no valid permit found, issue Stop Work Notice under MRTP Act Section 52.
4. Initiate demolition proceedings if construction exceeds permissible limits.
5. File case with District Collector if land falls under Forest/Government category.

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.