

■ Severity: MEDIUM | Risk Score: 50.0/100

Zone Details

Field	Value
Zone ID	live_52cc7ecf_3
Coordinates	19.432206°N, 72.970611°E
Constructed Area	0.40 hectares (4,000 sq metres)
Severity Level	MEDIUM
Risk Score	50.0 / 100
Primary Violation	LIVE SCAN RESULT

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	0.40 ha	Primary driver — larger = higher score
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2019 → 2023	4-year change window
Land Classification	LIVE SCAN RESULT	Determines violation severity
Final Score	50.0/100	Severity: MEDIUM

This zone received a MEDIUM score of 50.0/100 because the detected construction covers 0.40 hectares — between 0.2 and 1 hectare. This is a moderate unauthorized structure that warrants scheduled inspection.

Land Classification Note: Land classification pending verification.

Satellite Evidence

The images below show the flagged location in 2019 (before) and 2023 (after). Visible change in land cover — new grey/brown built-up area replacing green or open land — confirms the satellite detection.



Recommended Action

Schedule inspection

1. Add to inspection queue for next available field officer visit.
2. Check online permit records before physical inspection.
3. Issue advisory notice if minor violations found.

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.