

■ Severity: LOW | Risk Score: 13.3/100

Zone Details

| Field             | Value                           |
|-------------------|---------------------------------|
| Zone ID           | live_5fe86f78_21                |
| Coordinates       | 19.434117°N, 72.979933°E        |
| Constructed Area  | 0.10 hectares (1,000 sq metres) |
| Severity Level    | LOW                             |
| Risk Score        | 13.3 / 100                      |
| Primary Violation | LIVE SCAN RESULT                |

How the Risk Score Was Calculated

| Scoring Factor        | Value            | Contribution                           |
|-----------------------|------------------|----------------------------------------|
| Construction Area     | 0.10 ha          | Primary driver — larger = higher score |
| NDBI Change Magnitude | > 0.15 threshold | Confirms built-up area increase        |
| Time Period           | 2019 → 2023      | 4-year change window                   |
| Land Classification   | LIVE SCAN RESULT | Determines violation severity          |
| Final Score           | 13.3/100         | Severity: LOW                          |

This zone received a LOW score of 13.3/100 because the detected construction covers 1000 sq metres — a small structure that should be logged for routine inspection.

Land Classification Note: Land classification pending verification.

Satellite Evidence

The images below show the flagged location in 2019 (before) and 2023 (after). Visible change in land cover — new grey/brown built-up area replacing green or open land — confirms the satellite detection.



---

## Recommended Action

### Log for routine inspection

1. Log in municipal records for routine inspection cycle.
2. No immediate action required unless escalated by complaint.

---

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.