

■ Severity: CRITICAL | Risk Score: 99.0/100

Zone Details

Field	Value
Zone ID	82
Coordinates	19.495062°N, 72.806870°E
Constructed Area	51.69 hectares (516,905 sq metres)
Severity Level	CRITICAL
Risk Score	99.0 / 100
Violation Type	FOREST ENCROACHMENT
OSM Overlays	None
Legal Flags	None
Risk Boost	0.0

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	51.69 ha	Primary driver - larger = higher score
Land Classification	FOREST ENCROACHMENT	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2019 → 2023	Change detection window
Final Score	99.0/100	Severity: CRITICAL

This zone received a CRITICAL score of 99.0/100 because the detected construction covers 51.7 hectares - exceeding the 5-hectare threshold that indicates large-scale unauthorized development. Structures of this size cannot be accidental extensions and require immediate enforcement action.

Land Classification Note: The construction location falls within an area classified as protected forest or woodland by ISRO Bhuvan land use data. Construction on forest land without Forest Department clearance is prohibited under the Forest Conservation Act, 1980.

Satellite Evidence

The images below show the flagged location in 2019 (before) and 2023 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2019 - Before Construction



2023 - After Construction

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.