



Landslide Field Survey (NH 6 & NH 206, Meghalaya) following Extreme Rainfall Events on 30-31 May 2025



***North Eastern Regional Node for Disaster Risk Reduction (NER-DRR)
North Eastern Space Applications Centre, Dept of Space, Govt of India,
Umiam, Meghalaya***

Report on
Landslide Field Survey (NH 6 & NH 206, Meghalaya) following Extreme Rainfall Events on
30–31 May 2025

Submitted To
State Disaster Management Authority, Meghalaya



By
North Eastern Regional Node for Disaster Risk Reduction (NER-DRR)
North Eastern Space Applications Centre
Dept of Space, Govt of India
Umiam, Meghalaya-793103

1. Background

Between 30th and 31st May 2025, the North Eastern Region (NER) of India experienced an intense and widespread rainfall event under the active phase of the southwest monsoon. On 30th May, a deep depression that had crossed the India-Bangladesh coast intensified the monsoonal activity and was situated over north Bangladesh and adjoining Meghalaya, causing extremely heavy rainfall, especially over Assam, Meghalaya, Tripura, and Arunachal Pradesh. Meghalaya, in particular, witnessed isolated instances of exceptionally heavy rainfall. By 31st May, although the system had weakened into a less marked circulation, its remnants continued to influence the region, resulting in very heavy rainfall over Upper Assam, Arunachal Pradesh, and Meghalaya, accompanied by gusty winds and thunderstorms across all northeastern states. The meteorological conditions led to multiple landslides and other disaster events, severely impacting road connectivity, disrupting communication infrastructure, and tragically causing loss of human lives and property across the region, particularly in vulnerable hilly terrain including those in Meghalaya.

2. Objectives

- To conduct field-based mapping of landslides triggered by the 30th and 31st May 2025 rainfall event.
- To collect geospatial and photographic evidence for each landslide location.

3. Study Area

3.1 NH 6 Corridor (GS Road): Mawlai to Jorabat (Ri Bhoi & East Khasi Hills) (Figure 1).

- Date of Survey: 31st May 2025
- Rainfall Trigger: 30th May 2025
- Total Landslides Mapped: 28
- Coordinates & Data: Collected using GPS devices and Camera.

3.2 NH 206 Corridor: Shillong to Pynursla (East Khasi Hills) (Figure 1).

- Date of Survey: 1st June 2025
- Rainfall Trigger: 30th and 31st May 2025
- Total Landslides Mapped: 46
- Coordinates & Data: Collected using GPS devices and Camera.




Figure 1 Field Survey Location Map

4. Preliminary Observations

The field investigation following the extreme rainfall events of 30th and 31st May 2025 revealed several critical geomorphological and infrastructural characteristics that contributed to the widespread landslide activity along the surveyed road corridors in Meghalaya. Key observations are elaborated as follows:

- **Dominance of Shallow Translational Slides and Debris Flows:**

The majority of the landslides observed during the field survey were shallow in nature, typically occurring within the upper few meters of the soil and weathered rock profile. These failures were primarily translational slides where the displaced material moved downslope along planar surfaces. Many of these transitions evolved into debris flows due to the saturation of slope material and channelized runoff, particularly in locations where natural or artificial drainage paths were overwhelmed.

- **Role of Steep Slopes, Saturated Soil, and Poor Slope Management:**

The landslide-prone corridors, particularly NH 6 and NH 206, traverse highly dissected and steeply inclined terrain. The excessive rainfall resulted in high pore water pressure in the soil profile, significantly reducing slope stability. In several locations, the failure was exacerbated by unengineered cut slopes created during road widening or maintenance (Annexures). The absence of proper retaining structures or slope reinforcement measures made these sections particularly vulnerable to failure under wet conditions.

- **Multiple Road Blockages and Disruption of Connectivity:**

Landslides resulted in the deposition of debris directly onto the road surface, often blocking both lanes of traffic. Several sites had large volumes of soil, rocks, and vegetation completely covering road segments, making them impassable without mechanical intervention. This not only disrupted daily transportation but also hindered emergency response and relief operations, isolating communities along the affected routes.

- **Reactivation of Old Landslide Zones:**

Field evidence suggests that in multiple locations, landslides occurred at or near previously known failure zones. These legacy landslide scars likely remained unstable due to inadequate long-term stabilization and monitoring efforts. The combination of pre-existing weakness and renewed rainfall loading resulted in reactivation, highlighting the need for continued surveillance and hazard mitigation at historically unstable sites.

5. Impact and Damage Assessment

The landslide events of 30th and 31st May 2025, triggered by exceptional rainfall, caused extensive damage across the surveyed corridors in Meghalaya. The impact spanned transportation, infrastructure integrity, and the emergence of new landslide hazard-prone areas. The detailed assessment is as follows:

- **Transport Disruption:**

The landslides along NH 6 (Mawlai to Jorabat) and NH 206 (Shillong to Pynursla) led to significant obstruction of traffic due to debris deposition across the highways. In several locations, both lanes were completely blocked, halting the movement of vehicles and stranding commuters for hours. These disruptions affected not only local traffic but also essential inter-state connectivity. In some cases, alternate routes were unavailable or equally vulnerable, leading to widespread mobility challenges and logistical delays, particularly in the movement of emergency services, medical aid, and supplies.

- **Infrastructure Loss:**

The intense rainfall and associated slope failures caused notable damage to road infrastructure. Pavement surfaces were uplifted or eroded due to undercutting and debris impact. Retaining structures, where present, were often found to be either collapsed, tilted, or buried under debris, indicating structural failure or design inadequacy. In multiple locations, protective slope reinforcements were either absent or compromised. Road shoulders were also eroded in many stretches, increasing the vulnerability.

- **Emergence of High-Risk Zones:**

Field observations and photographic documentation suggest that many areas along NH 6 and NH 206 are now susceptible to further slope instability. The saturation of soil layers and the presence of tension cracks near the road edges indicate a high potential for delayed or secondary failures, especially if wet conditions persist. Some areas showed signs of creeping slopes and minor slumping, which may evolve into major landslides during future rainfall events. These high-risk zones necessitate urgent attention, detailed geotechnical evaluation, and implementation of long-term mitigation strategies to prevent further damage.

6. Recommendations

- Immediate Remediation: Mechanical clearance and stabilization
- Long-term Planning: Detailed investigation, bioengineering, and EWS.
- Policy Interventions: Incorporate susceptibility maps into planning.

7. Conclusion

The post-event field survey conducted along key transport corridors in Meghalaya—NH 6 (Mawlai to Jorabat) and NH 206 (Shillong to Pynursla) in the aftermath of the extreme rainfall episodes on 30th and 31st May 2025, has underscored the acute vulnerability of this region to rainfall-induced landslides. The observed slope failures, infrastructure damage, and transport disruptions are a clear manifestation of the fragile terrain characteristics, intense anthropogenic modification of slopes, and lack of adequate slope protection measures in place.

The survey documented 74 landslides in total across two days, many of which affected existing roads, drainage systems, and community access points. The concentration of shallow translational slides and debris flows, coupled with repeated reactivation of older landslide zones, indicates systemic issues in slope design, water management, and monitoring.

These findings emphasize the urgent need for a multi-pronged approach that includes:

- **Slope Stabilization Measures:** Immediate mechanical and bioengineering interventions are essential to prevent further failures, especially in areas with active or reactivated landslides.
- **Development of Resilient Infrastructure:** Future road construction and maintenance must integrate geotechnical investigations, proper slope grading, and engineered retaining systems to reduce vulnerability.
- **Implementation of Early Warning Systems (EWS):** Real-time rainfall monitoring, landslide threshold models, and community-based alert mechanisms must be institutionalized across high-risk corridors.
- **Integration into Planning Frameworks:** Landslide hazard zonation and susceptibility mapping should be mainstreamed into regional development plans, especially in areas undergoing road expansion, deforestation, or urban growth.

In conclusion, the increasing frequency and intensity of extreme weather events in the context of climate change demand proactive, science-driven strategies to mitigate the risk of landslides in Meghalaya and the broader North Eastern Region. The insights from this field survey should serve as a crucial input for state disaster management authorities, road planning agencies, and policy makers to enhance the region's resilience to future landslide events.

8. Annexures

- ✓ -Annexure I: Surveyed landslide location along NH 6
- ✓ -Annexure II: Surveyed landslide location along NH 206
- ✓ Annexure III: Photographic documentation.

Annexure I: Surveyed landslide location along NH 6

ID	SLIDE_ID	YEAR	MONTH	STATE	DISTRICT	LS_NAME	NH_SH_AFFECTED	LAT	LOX	DATE_OF_EVENT	STATUS	REMARKS
1998	Field Survey/2025/Meghalaya/31	2025	May	Meghalaya	Ri Bhoi	Umiam Landslide 7	NH 6	25.67923	91.89988	30-05-2025	Verified	Road Affected
1999	Field Survey/2025/Meghalaya/32	2025	May	Meghalaya	Ri Bhoi	Umbang Landslide	NH 6	25.68672	91.9034	30-05-2025	Verified	Road Affected
2000	Field Survey/2025/Meghalaya/33	2025	May	Meghalaya	Ri Bhoi	Umbang Landslide 2	NH 6	25.68624	91.90282	30-05-2025	Verified	Road Affected
2001	Field Survey/2025/Meghalaya/34	2025	May	Meghalaya	Ri Bhoi	Sumer Landslide 1	NH 6	25.69024	91.90534	30-05-2025	Verified	Road Affected
2002	Field Survey/2025/Meghalaya/35	2025	May	Meghalaya	Ri Bhoi	Umsamlem Landslide	NH 6	25.75852	91.87999	30-05-2025	Verified	Road Affected
2003	Field Survey/2025/Meghalaya/36	2025	May	Meghalaya	Ri Bhoi	Kwinain Landslide	NH 6	25.82308	91.87242	30-05-2025	Verified	Road Affected
2004	Field Survey/2025/Meghalaya/37	2025	May	Meghalaya	Ri Bhoi	Umnget Landslide	NH 6	25.81488	91.87571	30-05-2025	Verified	Road Affected
2005	Field Survey/2025/Meghalaya/38	2025	May	Meghalaya	Ri Bhoi	Umling Landslide	NH 6	25.92683	91.87521	30-05-2025	Verified	Road Affected
2006	Field Survey/2025/Meghalaya/39	2025	May	Meghalaya	Ri Bhoi	Umling Landslide 2	NH 6	25.92723	91.87506	30-05-2025	Verified	Road Affected
2007	Field Survey/2025/Meghalaya/40	2025	May	Meghalaya	Ri Bhoi	Umling Landslide 3	NH 6	25.95857	91.86467	30-05-2025	Verified	Road Affected
2008	Field Survey/2025/Meghalaya/41	2025	May	Meghalaya	Ri Bhoi	Umling Landslide 4	NH 6	25.9571	91.86125	30-05-2025	Verified	Road Affected
2009	Field Survey/2025/Meghalaya/42	2025	May	Meghalaya	Ri Bhoi	Byrnihat Landslide	NH 6	26.01556	91.86894	30-05-2025	Verified	Road Affected
2010	Field Survey/2025/Meghalaya/43	2025	May	Meghalaya	Ri Bhoi	Byrnihat Landslide 2	NH 6	26.0169	91.86662	30-05-2025	Verified	Road Affected
2011	Field Survey/2025/Meghalaya/44	2025	May	Meghalaya	Ri Bhoi	17 Mile Landslide	NH 6	26.02992	91.86895	30-05-2025	Verified	Road Affected
2012	Field Survey/2025/Meghalaya/45	2025	May	Meghalaya	Ri Bhoi	Byrnihat Landslide 3	NH 6	26.03532	91.86799	30-05-2025	Verified	Road Affected
2013	Field Survey/2025/Meghalaya/46	2025	May	Meghalaya	Ri Bhoi	Byrnihat Landslide 4	NH 6	26.03628	91.86832	30-05-2025	Verified	Road Affected
2014	Field Survey/2025/Meghalaya/47	2025	May	Meghalaya	Ri Bhoi	Ampher Landslide	NH 6	26.08904	91.87737	30-05-2025	Verified	Road Affected
2015	Field Survey/2025/Meghalaya/48	2025	May	Meghalaya	Ri Bhoi	Jorabat Landslide	NH 6	26.09923	91.87597	30-05-2025	Verified	Road Affected
2016	Field Survey/2025/Meghalaya/49	2025	May	Meghalaya	Ri Bhoi	Umsning Landslide	NH 6	25.70906	91.89498	30-05-2025	Verified	Road Affected
2017	Field Survey/2025/Meghalaya/50	2025	May	Meghalaya	Ri Bhoi	Umsning Landslide 2	NH 6	25.70907	91.895	30-05-2025	Verified	Road Affected
2018	Field Survey/2025/Meghalaya/51	2025	May	Meghalaya	Ri Bhoi	Umiam Landslide 8	NH 6	25.6792	91.89967	30-05-2025	Verified	Road Affected
2019	Field Survey/2025/Meghalaya/52	2025	May	Meghalaya	Ri Bhoi	Umiam Landslide 9	NH 6	25.67051	91.90494	30-05-2025	Verified	Road Affected
2020	Field Survey/2025/Meghalaya/53	2025	May	Meghalaya	Ri Bhoi	Umiam Landslide 10	NH 6	25.66272	91.90127	30-05-2025	Verified	Road Affected
2021	Field Survey/2025/Meghalaya/54	2025	May	Meghalaya	Ri Bhoi	Umiam Landslide 11	NH 6	25.66073	91.9014	30-05-2025	Verified	Road Affected
2022	Field Survey/2025/Meghalaya/55	2025	May	Meghalaya	East Khasi Hills	Umiam Landslide 12	NH 6	25.65293	91.89804	30-05-2025	Verified	Road Affected
2023	Field Survey/2025/Meghalaya/56	2025	May	Meghalaya	East Khasi Hills	ISBT Bypass Landslide 1	NH 6	25.62575	91.89703	30-05-2025	Verified	Road Affected
2024	Field Survey/2025/Meghalaya/57	2025	May	Meghalaya	East Khasi Hills	ISBT Bypass Landslide 2	NH 6	25.6248	91.91046	30-05-2025	Verified	Road Affected
2025	Field Survey/2025/Meghalaya/58	2025	May	Meghalaya	East Khasi Hills	ISBT Bypass Landslide 3	NH 6	25.62053	91.90989	30-05-2025	Verified	Road Affected

Annexure II: Surveyed landslide location along NH 206

ID	SLIDE_ID	YEAR	MONTH	STATE	DISTRICT	LS_NAME	NH_SH_AFFECTED	LAT	LON	DATE_OF_EVENT	STATUS	REMARKS
2039	Field Survey/2025/Meghalaya/72	2025	May	Meghalaya	East Khasi Hills	Mylliem Landslide 2	NH 206	25.49086	91.82135	30-05-2025	Verified	Road Affected
2040	Field Survey/2025/Meghalaya/73	2025	May	Meghalaya	East Khasi Hills	Mylliem Landslide 3	NH 206	25.48787	91.81959	30-05-2025	Verified	Road Affected
2041	Field Survey/2025/Meghalaya/74	2025	May	Meghalaya	East Khasi Hills	Mylliem Landslide 4	NH 206	25.48715	91.81948	30-05-2025	Verified	Road Affected
2042	Field Survey/2025/Meghalaya/75	2025	May	Meghalaya	East Khasi Hills	Mylliem Landslide 5	NH 206	25.4868	91.81987	30-05-2025	Verified	Road Affected
2043	Field Survey/2025/Meghalaya/76	2025	May	Meghalaya	East Khasi Hills	Mylliem Landslide 6	NH 206	25.47565	91.81801	30-05-2025	Verified	Road Affected
2044	Field Survey/2025/Meghalaya/77	2025	May	Meghalaya	East Khasi Hills	Mylliem Landslide 7	NH 206	25.47174	91.81621	31-05-2025	Verified	Road Affected
2045	Field Survey/2025/Meghalaya/78	2025	May	Meghalaya	East Khasi Hills	Mylliem Landslide 8	NH 206	25.47133	91.81608	30-05-2025	Verified	Road Affected
2046	Field Survey/2025/Meghalaya/79	2025	May	Meghalaya	East Khasi Hills	Mylliem Landslide 9	NH 206	25.46944	91.81748	30-05-2025	Verified	Road Affected
2047	Field Survey/2025/Meghalaya/80	2025	May	Meghalaya	East Khasi Hills	Mylliem Landslide 10	NH 206	25.46891	91.8184	30-05-2025	Verified	Road Affected
2048	Field Survey/2025/Meghalaya/81	2025	May	Meghalaya	East Khasi Hills	Mylliem Landslide 11	NH 206	25.46687	91.81902	31-05-2025	Verified	Road Affected
2049	Field Survey/2025/Meghalaya/82	2025	May	Meghalaya	East Khasi Hills	Mylliem Landslide 12	NH 206	25.46591	91.82085	31-05-2025	Verified	Road Affected
2050	Field Survey/2025/Meghalaya/83	2025	May	Meghalaya	East Khasi Hills	Mylliem Landslide 13	NH 206	25.46593	91.82263	30-05-2025	Verified	Road Affected
2051	Field Survey/2025/Meghalaya/84	2025	May	Meghalaya	East Khasi Hills	Umtyngar Landslide	NH 206	25.46529	91.82496	31-05-2025	Verified	Road Affected
2052	Field Survey/2025/Meghalaya/85	2025	May	Meghalaya	East Khasi Hills	Umtyngar Landslide 2	NH 206	25.46555	91.82614	30-05-2025	Verified	Road Affected
2053	Field Survey/2025/Meghalaya/86	2025	May	Meghalaya	East Khasi Hills	Umtyngar Landslide 3	NH 206	25.46443	91.82775	31-05-2025	Verified	Road Affected
2054	Field Survey/2025/Meghalaya/87	2025	May	Meghalaya	East Khasi Hills	Laitkroh Landslide	NH 206	25.46194	91.82976	31-05-2025	Verified	Road Affected
2055	Field Survey/2025/Meghalaya/88	2025	May	Meghalaya	East Khasi Hills	Laitkroh Landslide 2	NH 206	25.46117	91.83177	31-05-2025	Verified	Road Affected
2056	Field Survey/2025/Meghalaya/89	2025	May	Meghalaya	East Khasi Hills	Laitkroh Landslide 3	NH 206	25.44031	91.84712	30-05-2025	Verified	Road Affected
2057	Field Survey/2025/Meghalaya/90	2025	May	Meghalaya	East Khasi Hills	Laitkroh Landslide 4	NH 206	25.43961	91.8491	30-05-2025	Verified	Road Affected
2058	Field Survey/2025/Meghalaya/91	2025	May	Meghalaya	East Khasi Hills	Laitkroh Landslide 5	NH 206	25.43813	91.85107	30-05-2025	Verified	Road Affected
2059	Field Survey/2025/Meghalaya/92	2025	May	Meghalaya	East Khasi Hills	Lum Thnagding Landslide	NH 206	25.43763	91.85282	31-05-2025	Verified	Road Affected
2060	Field Survey/2025/Meghalaya/93	2025	May	Meghalaya	East Khasi Hills	Lum Thnagding Landslide 2	NH 206	25.43763	91.85432	30-05-2025	Verified	Road Affected
2061	Field Survey/2025/Meghalaya/94	2025	May	Meghalaya	East Khasi Hills	Lum Thnagding Landslide 3	NH 206	25.43707	91.8561	30-05-2025	Verified	Road Affected
2062	Field Survey/2025/Meghalaya/95	2025	May	Meghalaya	East Khasi Hills	Lum Thnagding Landslide 4	NH 206	25.437	91.85824	30-05-2025	Verified	Road Affected
2063	Field Survey/2025/Meghalaya/96	2025	May	Meghalaya	East Khasi Hills	Wah Bnoh Landslide	NH 206	25.43398	91.86066	31-05-2025	Verified	Road Affected
2064	Field Survey/2025/Meghalaya/97	2025	May	Meghalaya	East Khasi Hills	Wah Bnoh Landslide 2	NH 206	25.43231	91.86152	31-05-2025	Verified	Road Affected
2065	Field Survey/2025/Meghalaya/98	2025	May	Meghalaya	East Khasi Hills	Wah Bnoh Landslide 3	NH 206	25.43141	91.86274	31-05-2025	Verified	Road Affected
2066	Field Survey/2025/Meghalaya/99	2025	May	Meghalaya	East Khasi Hills	Wah Bnoh Landslide 4	NH 206	25.42705	91.86312	30-05-2025	Verified	Road Affected

ID	SLIDE_ID	YEAR	MONTH	STATE	DISTRICT	LS_NAME	NH_SH_AFFECTED	LAT	LON	DATE_OF_EVENT	STATUS	REMARKS
2067	Field Survey/2025/Meghalaya/100	2025	May	Meghalaya	East Khasi Hills	Wah Bnoh Landslide 5	NH 206	25.4229	91.86607	31-05-2025	Verified	Road Affected
2068	Field Survey/2025/Meghalaya/101	2025	May	Meghalaya	East Khasi Hills	Wah Bnoh Landslide 6	NH 206	25.42221	91.86785	31-05-2025	Verified	Road Affected
2069	Field Survey/2025/Meghalaya/102	2025	May	Meghalaya	East Khasi Hills	Pomlum Landslide	NH 206	25.42162	91.86807	31-05-2025	Verified	Road Affected
2070	Field Survey/2025/Meghalaya/103	2025	May	Meghalaya	East Khasi Hills	Pomlum Landslide 2	NH 206	25.42881	91.86459	30-05-2025	Verified	Road Affected
2071	Field Survey/2025/Meghalaya/104	2025	May	Meghalaya	East Khasi Hills	Pomlum Landslide 3	NH 206	25.41838	91.86815	31-05-2025	Verified	Road Affected
2072	Field Survey/2025/Meghalaya/105	2025	May	Meghalaya	East Khasi Hills	Pomlum Landslide 4	NH 206	25.41072	91.87425	30-05-2025	Verified	Road Affected
2073	Field Survey/2025/Meghalaya/106	2025	May	Meghalaya	East Khasi Hills	Mawkejam Landslide	NH 206	25.40375	91.87281	31-05-2025	Verified	Road Affected
2074	Field Survey/2025/Meghalaya/107	2025	May	Meghalaya	East Khasi Hills	Mawkejam Landslide 2	NH 206	25.39732	91.87258	31-05-2025	Verified	Road Affected
2075	Field Survey/2025/Meghalaya/108	2025	May	Meghalaya	East Khasi Hills	Mawkejam Landslide 3	NH 206	25.39072	91.87185	31-05-2025	Verified	Road Affected
2076	Field Survey/2025/Meghalaya/109	2025	May	Meghalaya	East Khasi Hills	Mawkejam Landslide 4	NH 206	25.3852	91.87428	31-05-2025	Verified	Road Affected
2077	Field Survey/2025/Meghalaya/110	2025	May	Meghalaya	East Khasi Hills	Rgnain Landslide	NH 206	25.38303	91.87442	31-05-2025	Verified	Road Affected
2078	Field Survey/2025/Meghalaya/111	2025	May	Meghalaya	East Khasi Hills	Rgnain Landslide 2	NH 206	25.38257	91.87439	30-05-2025	Verified	Road Affected
2079	Field Survey/2025/Meghalaya/112	2025	May	Meghalaya	East Khasi Hills	Rgnain Landslide 3	NH 206	25.37975	91.87347	31-05-2025	Verified	Road Affected
2080	Field Survey/2025/Meghalaya/113	2025	May	Meghalaya	East Khasi Hills	Rgnain Landslide 4	NH 206	25.37642	91.87452	31-05-2025	Verified	Road Affected
2081	Field Survey/2025/Meghalaya/114	2025	May	Meghalaya	East Khasi Hills	Kyntiew Masi Landslide	NH 206	25.36093	91.88129	30-05-2025	Verified	Road Affected
2082	Field Survey/2025/Meghalaya/115	2025	May	Meghalaya	East Khasi Hills	Kyntiew Masi Landslide 2	NH 206	25.3604	91.88673	30-05-2025	Verified	Road Affected
2083	Field Survey/2025/Meghalaya/116	2025	May	Meghalaya	East Khasi Hills	Langkyrdem Landslide	NH 206	25.35567	91.89466	31-05-2025	Verified	Road Affected
2084	Field Survey/2025/Meghalaya/117	2025	May	Meghalaya	East Khasi Hills	Langkyrdem Landslide 2	NH 206	25.34457	91.8906	30-05-2025	Verified	Road Affected

Annexure III: Photographic documentation (NH 6).

ID 1998



ID 1999



ID 2000



ID 2001



ID 2002



ID 2003



ID 2004



ID 2005



ID 2006



ID 2007



ID 2008



ID 2009



ID 2010



ID 2011



ID 2012



ID 2013



ID 2014



ID 2015




ID 2016



ID 2017



ID 2018



ID 2019




ID 2020



ID 2021



ID 2022



ID 2023



ID 2024



ID 2025



GPS Map Camera

Shillong, Meghalaya, India

GS Road, Mawlai, Shillong, Meghalaya
793022, India


Lat 25.620526, Long 91.909893

05/31/2025 04:10 PM GMT+05:30


Note : Captured by GPS Map Camera

Annexure III: Photographic documentation (NH 206).

ID 2039



ID 2040



ID 2041



ID 2042



ID 2043



ID 2044



ID 2045



ID 2046




ID 2047



ID 2048



ID 2049



ID 2050



ID 2051



ID 2052



ID 2053



ID 2054




ID 2055



ID 2056




ID 2057



ID 2058




ID 2059



ID 2060




ID 2061



ID 2062



ID 2063




ID 2064




ID 2065



ID 2066



ID 2067



ID 2068




ID 2069




ID 2070



ID 2071



ID 2072



ID 2073



ID 2074



ID 2075



ID 2076



ID 2077



ID 2078




ID 2079



ID 2080



ID 2081




ID 2082



ID 2083



ID 2084



Disclaimer: This report is solely based on field surveys and is intended for use in disaster management planning. It should not be used for any legal proceedings or claims.