

IOT LAB-3 Shreyas.M 1BM18CS105 PUSHBUTTON Program int buttonstake = 0; void setup() pinmode (13 OUTPUT) void loop () button state = digital Read (2); if (buttonstate = = HIGH) digital waite (13, HIGH); else digital Waite (13, LOW);