

OIL INDIA LIMITED

HSE / NEAR-MISS REPORT

Report ID	SIFRA-NM-2026-0905-001
Worker ID	OIL-W-209
Date	05 September 2026
Time Observed	10:35 hrs
Location	Amravati Operational Site — Process/Pressure Testing Area
Report Type	Near Miss / Unsafe Act & Unsafe Condition
Reported By	HSC Safety Officer

1. INCIDENT / NEAR-MISS NARRATIVE

During pressure-testing and line-up activity at the Amravati operational site, a worker was observed approaching a pressurized hydrocarbon line to operate a manual valve. The line had not been positively isolated and the Lock-Out/Tag-Out (LOTO) verification was not confirmed before the valve operation was attempted. A temporary exclusion barrier was also incomplete, leaving personnel within the potential line-of-fire zone. The activity was stopped immediately by the safety observer before any release, injury, or equipment damage occurred.

2. IMMEDIATE HAZARD / POTENTIAL CONSEQUENCE

The combination of stored pressure, potential hydrocarbon release, incomplete isolation verification, and personnel exposure to the line-of-fire area created a credible potential for a high-energy release. A loss of containment could have resulted in serious injury or fatality through pressure exposure, hydrocarbon release, fire, or explosion.

3. UNSAFE ACTS (UA)

- Attempting valve operation before positive isolation and LOTO verification.
- Entering/working close to a potential line-of-fire zone before controls were confirmed.

4. UNSAFE CONDITIONS (UC)

- LOTO verification was not confirmed at the isolation point.
- Incomplete exclusion barrier around the pressurized-line work area.
- Potential stored pressure remained in the process line.

5. CRITICAL SAFETY BARRIERS INVOLVED

- Positive Energy Isolation / Lock-Out-Tag-Out (LOTO) verification.
- Pressure bleed-off and zero-energy verification before line operation.
- Line-of-fire exclusion zone and physical barricading.
- Gas detection and emergency shutdown readiness.
- Appropriate PPE and authorized-work verification.

6. POTENTIAL IOGP LIFE-SAVING RULES

- Energy Isolation / LOTO
- Line of Fire

- Bypassing Safety Controls

7. CORRECTIVE ACTIONS TAKEN

- Work stopped immediately.
- Personnel moved outside the potential line-of-fire zone.
- Isolation status was re-verified before further work.
- Exclusion barricading was restored.
- Supervisor and HSE representative were notified.

8. RISK ASSESSMENT — HIGH POTENTIAL FATALITY

Risk Dimension	Assessment
Potential Severity	FATAL — credible serious injury/fatality consequence
Exposure	Personnel exposed near pressurized process equipment
Barrier Failure	LOTO/isolation verification and exclusion controls not confirmed
SIF Potential	HIGH
Fatality Potential	HIGH

HSE Classification: Near Miss — High SIF / High Potential Fatality event. No injury occurred because the activity was stopped before loss of containment or exposure.

This document is synthetic test data intended to validate the SIFRA AI incident-analysis workflow.