

Oil India Limited — HSE Division

Daily Field Near-Miss Observation Log — Batch Upload for SIFRA AI Processing

Reporting Officer	OIL-HSE-001 (R. Sharma, Shift HSE Officer)
Log Date	11-Sep-2026
Shift	Day Shift (06:00 - 18:00)
Facility	OIL Duliajan Field Complex, Assam
Number of Worker Entries	8

Instructions to AI Agent: Each entry below corresponds to one (1) worker observed by the HSE officer during today's field rounds. Process each entry independently through the SIF risk model and RAG pipeline and generate one Trust Report per Worker ID.

Entry 1 — Worker ID: OIL-W-101

Location / Site	Duliajan Field Complex — Wellhead Manifold Yard, Zone 2
Time Observed	08:15 hrs

Near-Miss / Unsafe Act-Condition Description (Officer's field notes):
Observed worker attempting to open a valve on the wellhead manifold before confirming the Lockout/Tagout (LOTO) pin was fully engaged. No LOTO verification tag was visible on the isolation point. Worker was instructed to stop and re-verify isolation before proceeding.

Entry 2 — Worker ID: OIL-W-102

Location / Site	Duliajan Field Complex — Drilling Rig Floor, Derrick Platform
Time Observed	09:40 hrs

Near-Miss / Unsafe Act-Condition Description (Officer's field notes):
Worker was seen on the elevated pipe rack (approx. 3.5 m) with safety harness worn but lanyard not clipped to a certified anchor point. Corrected on site; harness re-anchored before work resumed.

Entry 3 — Worker ID: OIL-W-103

Location / Site	Duliajan Field Complex — Separator Tank Farm
Time Observed	10:05 hrs

Near-Miss / Unsafe Act-Condition Description (Officer's field notes):
Hot work (grinding) was in progress near separator tank without a visible Hot Work Permit posted at the work site. Gas test reading was not recorded on the permit board at time of observation.

Entry 4 — Worker ID: OIL-W-104

Location / Site	Duliajan Field Complex — Crude Oil Storage Yard
Time Observed	11:20 hrs

Near-Miss / Unsafe Act-Condition Description (Officer's field notes):

Minor oil spill (approx. 1 sq. m) noted near storage tank access ladder, creating a slip hazard. No spill kit was deployed at the time of observation. Area was barricaded pending cleanup.

Entry 5 — Worker ID: OIL-W-105

Location / Site	Duliajan Field Complex — Mud Pit / Confined Space Entry Point
Time Observed	12:50 hrs

Near-Miss / Unsafe Act-Condition Description (Officer's field notes):

Worker requested entry into the mud pit for cleaning without a Confined Space Entry Permit on file and no attendant stationed at the entrance. Entry was halted until permit and atmospheric testing were completed.

Entry 6 — Worker ID: OIL-W-106

Location / Site	Duliajan Field Complex — Crane & Rigging Bay
Time Observed	13:30 hrs

Near-Miss / Unsafe Act-Condition Description (Officer's field notes):

During a lifting operation, a second worker was observed briefly walking beneath a suspended load while repositioning a tagline. Lift was paused and the crew re-briefed on exclusion-zone boundaries.

Entry 7 — Worker ID: OIL-W-107

Location / Site	Duliajan Field Complex — Site Access Road, Gate 3
Time Observed	14:10 hrs

Near-Miss / Unsafe Act-Condition Description (Officer's field notes):

Site utility vehicle observed exceeding the posted 20 km/h internal speed limit near the pedestrian crossing at Gate 3. Driver was not wearing a seatbelt at time of observation.

Entry 8 — Worker ID: OIL-W-108

Location / Site	Duliajan Field Complex — Electrical Substation, Panel Room B
Time Observed	15:45 hrs

Near-Miss / Unsafe Act-Condition Description (Officer's field notes):

Exposed electrical wiring found near Panel Room B junction box, with the protective cover panel left detached on the floor. No warning tape or signage was placed around the immediate area.

— End of batch log. 8 worker entries submitted for AI risk analysis and quiz generation. —