Control_of_motors_on off_NO_NC_Out / PLC_1 [CPU 1215C DC/DC/DC] / Program blocks

Main [OB1]

Main Properties					
General					
Name	Main	**Number**	1	**Type**	OB
Language	LAD	**Numbering**	Automatic		
Information					
Title	"Main Program Sweep (Cycle)"	**Author**	SHREYASH_GHADGE	**Comment**	- - - When Input 1 and Input 2 are OFF, Motor 1 & Motor 2 should be ON and Motor 3 & Motor 4 should be OFF. When Input 1 is OFF and Input 2 is ON, Motor 2 & Motor 3 should become ON and Motor 1 & Motor 4 should become OFF. When Input 1 is ON and Input 2 is OFF, Motor 3 & Motor 4 should become ON and Motor 1 & Motor 2 should become OFF. When Input 1 and Input 2 are ON, Motor 1 & Motor 4 should become ON and Motor 2 & Motor 3 should become OFF.
Family		**Version**	0.1	**User-defined ID**	

Main			
Name	**Data type**	**Default value**	**Comment**
Input			
Initial_Call	Bool		Initial call of this OB
Remanence	Bool		=True, if remanent data are available
Temp			
Constant			

Network 1: MOTOR_1



Network 2: MOTOR_2



Network 3: MOTOR_3



Network 4: MOTOR_4