

TECHNICIAN LOG

Machine ID: MX-01

Technician: Ravi Kumar

Observed Temperature: 91°C

Issue: Unusual vibration detected.

TECHNICIAN OBSERVATIONS

Issue: Unusual noise detected.

Cooling System: Requires inspection.

Action Taken: Machine stopped for further inspection.

Yes