

Product 1 Rotary Knob

Base: F01_Rotary_Fixture (base type A; any base of type A fits) · Build 01 → 04. Dismantle 04 → 01. All real parts are black PLA (colours here are for clarity).


0 Base on the table




1 Add M1_01 Housing




2 Add M1_02 Spindle Carrier




3 Add M1_03 Rotary Knob



4 Add M1_04 Rear Guard



Exploded: parts go straight down onto the base, in order




Step	Part	Gripper	Look-alikes (check with wrist camera)
01	M1_01 Housing	normal	M2_01
02	M1_02 Spindle Carrier	normal	M2_02
03	M1_03 Rotary Knob	normal	none
04	M1_04 Rear Guard	normal	M2_04

Dismantle: remove 04, then 03, then 02, then 01 (straight up). The base never moves.


Product 2 Indicator Light

Base: F02_Indicator_Fixture (base type A; any base of type A fits) · Build 01 → 04. Dismantle 04 → 01. All real parts are black PLA (colours here are for clarity).


0 Base on the table




1 Add M2_01 Housing




2 Add M2_02 Diffuser Carrier




3 Add M2_03 Indicator Cap



4 Add M2_04 Rear Guard



Exploded: parts go straight down onto the base, in order




Step	Part	Gripper	Look-alikes (check with wrist camera)
01	M2_01 Housing	normal	M1_01
02	M2_02 Diffuser Carrier	normal	M1_02
03	M2_03 Indicator Cap	normal	none
04	M2_04 Rear Guard	normal	M1_04, M3_04

Dismantle: remove 04, then 03, then 02, then 01 (straight up). The base never moves.


Product 3 Push Button

Base: F03_Pushbutton_Fixture (base type B; any base of type B fits) · Build 01 → 04. Dismantle 04 → 01. All real parts are black PLA (colours here are for clarity).


0 Base on the table




1 Add M3_01 Housing




2 Add M3_02 Actuator Stem




3 Add M3_03 Button Cap



4 Add M3_04 Rear Guard



Exploded: parts go straight down onto the base, in order




Step	Part	Gripper	Look-alikes (check with wrist camera)
01	M3_01 Housing	normal	none
02	M3_02 Actuator Stem	normal	none
03	M3_03 Button Cap	normal	none
04	M3_04 Rear Guard	normal	M2_04

Dismantle: remove 04, then 03, then 02, then 01 (straight up). The base never moves.


Product 4 Sensor Connector

Base: F04_Sensor_Connector_Fixture (base type C; any base of type C fits) · Build 01 → 04. Dismantle 04 → 01. All real parts are black PLA (colours here are for clarity).


0 Base on the table




1 Add M4_01 Housing




2 Add M4_02 Sensor Insert




3 Add M4_03 Upper Guide



4 Add M4_04 Top Lock



Exploded: parts go straight down onto the base, in order




Step	Part	Gripper	Look-alikes (check with wrist camera)
01	M4_01 Housing	turn gripper 90°	M5_01, M6_01
02	M4_02 Sensor Insert	normal	none
03	M4_03 Upper Guide	normal	M5_03, M6_03
04	M4_04 Top Lock	normal	M5_04, M6_04

Dismantle: remove 04, then 03, then 02, then 01 (straight up). The base never moves.


Product 5 Control Io Connector

Base: F05_IO_Connector_Fixture (base type C; any base of type C fits) · Build 01 → 04. Dismantle 04 → 01. All real parts are black PLA (colours here are for clarity).


0 Base on the table




1 Add M5_01 Housing




2 Add M5_02 IO Insert




3 Add M5_03 Alignment Guide



4 Add M5_04 Service Lock



Exploded: parts go straight down onto the base, in order




Step	Part	Gripper	Look-alikes (check with wrist camera)
01	M5_01 Housing	turn gripper 90°	M4_01, M6_01
02	M5_02 IO Insert	normal	none
03	M5_03 Alignment Guide	normal	M4_03, M6_03
04	M5_04 Service Lock	normal	M4_04, M6_04

Dismantle: remove 04, then 03, then 02, then 01 (straight up). The base never moves.


Product 6 Power Connector

Base: F06_Power_Connector_Fixture (base type C; any base of type C fits) · Build 01 → 04. Dismantle 04 → 01. All real parts are black PLA (colours here are for clarity).


0 Base on the table




1 Add M6_01 Housing




2 Add M6_02 Power Insert




3 Add M6_03 Power Guide



4 Add M6_04 Power Lock



Exploded: parts go straight down onto the base, in order



Step	Part	Gripper	Look-alikes (check with wrist camera)
01	M6_01 Housing	turn gripper 90°	M4_01, M5_01
02	M6_02 Power Insert	normal	none
03	M6_03 Power Guide	normal	M4_03, M5_03
04	M6_04 Power Lock	normal	M4_04, M5_04

Dismantle: remove 04, then 03, then 02, then 01 (straight up). The base never moves.