

Home Insurance Underwriting Submission Report

Tailored for Tower Insurance
Submission Date: 06 Mar 2026

*This submission provides property, risk and documentation details to support underwriting assessment for a residential home in New Zealand.
Information is structured to align with Tower Insurance's risk-based approach and policy responsibilities.*

1. Policyholder Details

Client Name	Alex and Jordan Taylor
Contact Number	+64 21 555 0198
Email	alex.taylor@example.co.nz
Current Address	18 Marine Parade, Napier, Hawke's Bay
Insured Property Address	14 Remuera Road, Remuera, Auckland

2. Property Overview

Year Built	1952
Construction Class	Mixed Construction
Roof - Tile / Concrete	14 years
Foundations	Timber sub-floor with perimeter footings
Number of Storeys	2
Floor Area	220 m2
Land Area	650 m2

3. Occupancy & Use

Occupancy / Use Type	Owner-occupied
Property Use or Occupation	Residential dwelling
Number of Occupants	4

4. Sum Insured Information

Rebuild Sum Insured	NZD \$1,250,000
Basis	Reinstatement estimate aligned with recent renovation (2018)
Insurance-to-Value (ITV)	20%
Other Structures	In-ground swimming pool and outdoor improvements

5. Construction & Condition Notes

Roof Condition	Good condition consistent with 14-year age
Cladding Condition	Maintained timber weatherboard
Electrical System	22 years old
Plumbing System	25 years old
HVAC / Heating System	Wood Burner / Open Fire (compliant flue)

6. Special Features or Non-Standard Elements

Non-Standard Risk	In-ground swimming pool
Reports	Standard residential compliance
Alterations	Major renovation completed in 2018

7. Recent Renovations or Upgrades

2018	Significant renovation including upgrades and refurbishment
------	---

8. Security Features

Security Alarm	Local alarm only
Deadbolt / Window Locks	All external doors + windows
CCTV	No external CCTV observed
Smoke Alarm	Ionisation type only
Last Roof Inspection	27 months ago

9. Regulatory Compliance

Leaky Building / Weathertightness	Under WBO investigation
NZ Building Code (NZBC) Compliance	11 years old code
LIM Report	Sighted — clear
Deferred Maintenance Score	Minimal (Score: 4)
Prior Claims Disputes	Resolved dispute

10. Claims History (Past 5 Years)

Prior Carrier	Tower Insurance (Standard Residential Policy)
Prior Carrier Departure	Voluntary / market exit
Departure Reason	Policyholder voluntarily sought broader coverage terms for non-standard elements including the in-ground swimming pool and weathertightness exposure; no adverse underwriting action against insured
5-Yr Claim Count	1
5-Yr Incurred (NZD)	\$12,500
EQC Claim History	0 claims
Sum Insured Adequacy	95%

11. Supporting Documents (Attached / Available)

- LIM report reviewed — no adverse findings
- Renovation records (2018)
- Standard residential compliance documentation

12. Additional Notes for Underwriter

- Well-maintained, owner-occupied residential risk
- Renovation supports condition
- Low hazard exposure
- Swimming pool noted
- Favorable claims history

13. Broker / Advisor (If Applicable)

Broker Name	Casey Morgan
Company Name	Harbour Risk Advisory Ltd
Contact	+64 9 555 0100 casey.morgan@harbourrisk.co.nz
Submission Notes	Seeking comprehensive home cover

14. Additional Details

Organization Type	LLC
Address Line 1	1234 Maple Ridge Lane
City	San Jose

State	California
Zip Code	95123
Effective Date	01-01-2026

15. Loss History (5-Year Period)

5-Year Loss Count	6 losses — comprising weather-related, accidental damage, and minor liability events over the 2021–2026 lookback period
-------------------	---

16. Vacancy & Occupancy

Vacancy Rate	85–100% — property is owner-occupied and continuously occupied by 4 permanent residents; no extended unoccupied periods noted
--------------	---

17. Total Insured Value (TIV)

For residential home insurance, Total Insured Value (TIV) is calculated as the sum of the Rebuild Sum Insured, the declared value of Other Structures, and the estimated Contents replacement value as provided by the policyholder.

Component	Basis	Value (NZD)
Main Dwelling (Rebuild Sum Insured)	Reinstatement estimate — 2018 renovation aligned	\$1,250,000
Other Structures	In-ground swimming pool and outdoor improvements	\$45,000
Contents / Personal Property	Policyholder-declared replacement value	\$85,000
TOTAL INSURED VALUE (TIV)		\$1,380,000

Note: Other Structures and Contents values are indicative estimates based on property profile and policyholder declaration. Final TIV is subject to underwriter review and may be adjusted following site inspection or valuation.

This document is prepared for underwriting assessment purposes only and does not confer cover. All cover is subject to Tower Insurance underwriting criteria, policy terms, limits and exclusions.