

AI Bone Fracture Analysis Report



Result: No Fracture

Confidence: 99.80999755859375 %

Diagnosis:

No Fracture Detected

Summary:

The X-ray image does not show clear signs of a bone fracture.

Possible Causes:

- Muscle strain
- Ligament injury
- Minor impact trauma

Care Advice:

- Rest the affected area
- Apply ice if there is pain or swelling
- Monitor symptoms for 24–48 hours
- Consult a doctor if pain persists

■ This is an AI-assisted analysis and not a medical diagnosis. Please consult a qualified medical professional.

© SHUBHAM MADDHESIYA