

Approval Note TASK-A015B0F0

Analysis & Generated Response

Mock AI analysis generated successfully.

Grounding & Evidence Sources

- **Safety_Manual.txt** (Referenced): ure vessels shall not exceed 7.5 bar under routine operation. Any reading above this threshold must be flagged as a safety violation and esc
- **Maintenance_Guidelines.txt** (Referenced): MAINTENANCE GUIDELINES — Torque and Fastening. Section 4.1: Flange assembly A-2 fasteners shall be torqued to 220 Nm +/- 5 Nm and re-verify