

Document Summary TASK-CA5526D9

Analysis & Generated Response

Key Findings & Recommendations:

1. Flange Assembly A-2 Fasteners Torquing (Section 4.1):

- The torque specification for flange assembly A-2 fasteners is ± 5 Nm, with a maximum operating pressure of 7.5 bar.
- This recommendation ensures that all fastening operations adhere to the specified torque and pressure limits.

2. Maintenance Activity Approval (Section 4.9):

- Any maintenance activity must be accompanied by a signed lockout-tagout certificate attached to the work order.
- This requirement is necessary for ensuring compliance with safety standards and preventing unauthorized access or modifications during maintenance activities.

3. Pressure Vessel Operation Limits:

- Section 4.2 of the Safety Manual specifies that pressure vessels should not exceed 7.5 bar under routine operation.
- This recommendation ensures that all pressure systems are within safe operating limits, protecting against potential overpressure incidents and ensuring compliance with regulatory requirements.

4. Root-Cause Analysis for Vibration (Section 4.9):

- Section 4.9 of the Safety Manual mandates root-cause analysis before clearance.
- This recommendation is crucial in preventing equipment failures due to unexpected vibration or other operational issues, thereby enhancing system reliability and safety.

5. Lockout-tagout Certificate Requirement:

- The document specifies that a lockout/tagout certificate must be provided for any maintenance activity involving pressure systems.
- This requirement ensures that all potential hazards are identified and addressed before any work commences, promoting safer operations in industrial environments.

6. Vibration Monitoring (Section 7):

- Section 7 of the Safety Manual mandates vibration monitoring to ensure compliance with safety standards.
- Regular vibration analysis helps identify areas for improvement or maintenance needs, maintaining equipment performance within acceptable limits and reducing potential hazards.

Grounding & Evidence Sources:

- Maintenance_Guidelines.txt: MAINTENANCE GUIDELINES — Torque and Fastening.

Section 4.1: Flange assembly A-2 fasteners shall be torqued to 220 Nm +/- 5 Nm and re-verify

- TURBINE SOP v3 — Pressure Systems. Section 7.2: No maintenance activity shall commence without a signed lockout-tagout certificate attached
- This section mandates that any maintenance activity must be accompanied by a signed lockout-tagout certificate

Grounding & Evidence Sources

- **Adrestia_Report_TASK-B39A42C4.pdf** (Referenced): Approval Note TASK-B39A42C4 Analysis & Generated Response ■ Key Findings & Recommendations: 1. Flange Assembly A-2 Fasteners Torquing (Secti