

Document Summary TASK-CBAE422C

Analysis & Generated Response

Mock code generated successfully.

Grounding & Evidence Sources

- **Turbine_SOP.txt** (Referenced): ce activity shall commence without a signed lockout-tagout certificate attached to the work order. Maximum operating pressure 7.5 bar.
- **Maintenance_Guidelines.txt** (Referenced): MAINTENANCE GUIDELINES — Torque and Fastening. Section 4.1: Flange assembly A-2 fasteners shall be torqued to 220 Nm +/- 5 Nm and re-verify
- **Safety_Manual.txt** (Referenced): -cause analysis before clearance. Section 7: Lockout-tagout certificate is mandatory before any maintenance activity.