
P4: SPS power transfer and circulating current
nV2/V1 = 0.75
nV2/V1 = 1
nV2/V1 = 1.25
a
Power direction and magnitude
Transferred power (W)
40
20
0
−20
−40
−90
−45
0
45
90
Phase shift (degrees)
b
Current under voltage mismatch
Primary RMS current (A)
2.5
2.0
1.5
1.0
0.5
0.0
−90
−45
0
45
90
Phase shift (degrees)
Ideal periodic simulation | 39 points | No loss or ZVS model