obj-m += exception_driver.o

KDIR := /lib/modules/\$(shell uname -r)/build

PWD := \$(shell pwd)

all:

make -C \$(KDIR) M=\$(PWD) modules

clean:

make -C \$(KDIR) M=\$(PWD) clean