
(a) held-out normal
(b) unseen fault scenarios
expert
discovered
empty
perfect calibration
randomized quantile residual
normal quantile
normal quantile
8
6
4
2
0
−2
−4
−6
−8
−4
−2
0
2
4