

- 27** In an ideal transformer, the most important purpose of the soft iron core is to
- A** reduce eddy currents.
 - B** reduce the resistance of the coils.
 - C** reduce the effect of the Earth's magnetic field.
 - D** increase the flux linkage between the coils when a current flows through it.

