

**26** Which of the following minimises the energy loss in a transformer core due to eddy currents?

- A** Use of a steel core.
- B** Use of a higher frequency primary voltage.
- C** Use of a laminated core.
- D** Use of a primary coil with smaller resistivity.