

used to manufacture the coil. Hence B is an incorrect statement.

28.

Ans: **D**

$$V_s = \frac{N_s}{N_p} V_p = \frac{150}{1} (600) = 90000 \text{ V}$$

$$I_s = \frac{P}{V_s} = \frac{10 \times 10^6}{90000} = 111 \text{ A}$$

$$P_{loss} = I_s^2 R_{cables} = (111)^2 (20) = 250 \text{ kW}$$