/home/merofeev/leisure/tortila/flat_uho.scad

-60

-80

-100

Sqale is to calibrate actual printed dimension. Check both X and Y. Measure between tick 0 and last tick