

Suggested Magnetics

GENERAL DESCRIPTION

It is the purpose of this document to provide a list of suggested magnetics for use with the Microchip LAN family of products. The manufacturer, part number, package, number of cores, operating temperature range, and configuration are included for each suggested magnetic. Each product family table is categorized into "Qualified Magnetics" and "Suggested Magnetics" as defined below:

QUALIFIED MAGNETICS

Magnetics listed under this heading have been tested in order to verify proper operation with the specific Microchip device listed with it. The testing accomplished has been either formal UNH 100BASE-TX PMD testing, UNH 10BASE-T MAU testing and/or in-house testing performed by Microchip. The designer can assume with a high degree of confidence, that with proper PCB design techniques, the combinations of Microchip devices and magnetics presented in this category will perform to the highest standards.

SUGGESTED MAGNETICS

Magnetics listed under this heading have *not* been tested in order to verify proper operation with the specific Microchip device listed with it. This category of magnetic has been evaluated by the contents of the vendor supplied data sheet and legacy performance only. However, the designer can assume with some degree of confidence, that with proper PCB design techniques, the combinations of Microchip devices and magnetics presented in this category will perform to high standards. Magnetics in this category have been targeted for future Qualification Testing. Magnetics in this category may or may not advance to the Qualified Magnetics category. It is important to note, there is the remote possibility that a Suggested Magnetic, upon failing Qualification Testing, may be removed from the Suggested Magnetic category at any time by Microchip.

LAN8187, LAN8700, LAN8710, LAN8720, LAN9131, LAN9132, LAN9210, LAN9211, LAN9215, LAN9217, LAN9218, LAN9220, LAN9221, LAN9303, LAN9303M, LAN9311, LAN9312, LAN9313, LAN9420, LAN9500, LAN9500A, LAN9512, LAN9513, LAN9514

	Qualified Magnetics								
Vendor	Part Number	Package	Cores	Temp	Configuration				
Pulse	H1102	16-pin SOIC	4	0° - +70° C	HP Auto-MDIX				
Halo	TG110-RP55N5	16-pin SOIC	4	0° - +70° C	HP Auto-MDIX				
Halo	HFJ11-RP26E- L12RL	Integrated RJ45	4	0° - +70° C	HP Auto-MDIX POE				
		•							
Delta	RJSE1R5310A	Integrated RJ45	4	0° - +70° C	HP Auto-MDIX				
		Suggested Magnetic	cs						
Pulse	J0011D01B	Integrated RJ45	4	0° - +70° C	HP Auto-MDIX				
Midcom	000-7219-35	Cardbus	4	0° - +70° C	HP Auto-MDIX				
Bothhand	TS6121C	16-pin SOIC	4	0° - +70° C	HP Auto-MDIX				
Bothhand	LU1S041X-43	Integrated RJ45	4	0° - +70° C	HP Auto-MDIX				

LAN8187i, LAN8700i, LAN8710i, LAN8720i, LAN9215i, LAN9218i, LAN9221i, LAN9303i, LAN9303Mi, LAN9311i, LAN9313i, LAN9420i, LAN9500i, LAN9500Ai, LAN9512i, LAN9513i, LAN9514i

	Qualified Magnetics								
Vendor	Part Number	Package	Cores	Temp	Configuration				
Pulse	HX1188	16-pin SOIC	4	-40° - +85° C	HP Auto-MDIX				
Halo	TG110-RPE5N5	16-pin SOIC	4	-40° - +85° C	HP Auto-MDIX				
Halo	HFJ11-RPE26E- L12RL	Integrated RJ45	4	-40° - +85° C	HP Auto-MDIX POE				
TDK	TLA-6T717W	Integrated RJ45	4	-40° - +85° C	HP Auto-MDIX				
Delta	LFE8505T	16-pin SOIC	4	-40° - +85° C	HP Auto-MDIX				
		Suggested Magnetic	cs						
Midcom	000-7090-37R	16-pin SOIC	4	-40° - +85° C	HP Auto-MDIX				
Midcom	MIC66211-5171T- LF3	Integrated RJ45	4	-40° - +85° C	HP Auto-MDIX POE				
Elec & Eltek	820-M0323R	16-pin SOIC	4	-40° - +85° C	HP Auto-MDIX				

LAN7500								
Qualified Magnetics								
Vendor	Part Number	Package	Cores	Temp	Configuration			
Halo	HFJ11-1G02E	Integrated RJ45	8	0° - +70° C	HP Auto-MDIX			
Suggested Magnetics								
Halo	TG1G-S002NZRL	24-pin SOIC-W	8	0° - +70° C	HP Auto-MDIX			

LAN8810i, LAN7500i							
Suggested Magnetics							
Vendor	Vendor Part Number Package Cores Temp Configuration						
Halo	TG1G-E012NZRL	24-pin SOIC-W	8	-40° - +85° C	HP Auto-MDIX		

LAN89218, LAN89303								
Suggested Magnetics								
Vendor	Part Number	Package	Cores	Temp	Configuration			
Halo	TG110-AE050N5	16-pin SOIC	4	-40° - +85° C	HP Auto-MDIX			
Halo	TG110-AEX50N5LF	16-pin SOIC	4	-40° - +125° C	HP Auto-MDIX			

	LAN83C185, L	AN9115, LAN9116, L	.AN9117, LA	N9118				
Qualified Magnetics								
Vendor	Part Number	Package	Cores	Temp	Configuration			
Bel Fuse	S558-5999-46	16-pin SOP	5	0° - +70° C	10/100 Legacy			
Elec & Eltek	820-00278H	16-pin SOP	5	0° - +70° C	10/100 Legacy			
		Suggested Magnet						
Pulse	H1086	16-pin SOP	5	0° - +70° C	10/100 Legacy			
Pulse	H1012	16-pin SOP	5	0° - +70° C	10/100 Legacy			
Pulse	H1138	16-pin SOP	5	0° - +70° C	10/100 Legacy			
Pulse	PE-68515L	16-pin SOP	5	0° - +70° C	10/100 Legacy			
Pulse	H1089	16-pin SOP	4	0° - +70° C	10/100 Legacy			
Pulse (Valor)	ST6118T	16-pin SOP	5	0° - +70° C	10/100 Legacy			
Halo	TG22-3506NL	16-pin SOP	5	0° - +70° C	10/100 Legacy			
Halo	TG22-3506ND	16-pin SOP	5	0° - +70° C	10/100 Legacy			
Midcom	000-6241-37R	16-pin SOP	5	-40° - +85° C Note 1	10/100 Legacy			
Midcom	000-6181-37R	16-pin SOP	5	-40° - +85° C Note 1	10/100 Legacy			
				1	1			
YCL	20PMT04	16-pin SOP	5	0° - +70° C	10/100 Legacy			
YCL	PT163035	16-pin SOP	5	0° - +70° C	10/100 Legacy			
Transpower (Coev)	HB614	16-pin SOP	5	0° - +70° C	10/100 Legacy			
. , ,		•	5	0° - +70° C				
Transpower (Coev)	HB614-LP	16-pin SOP	5	0°-+70°C	10/100 Legacy			
XFMRS	XFATM6	16-pin SOP	5	-40° - +85° C Note 1	10/100 Legacy			
TDV	TI A 6T400	16 nin 200	-	0° - +70° C	40/400 5755			
TDK	TLA-6T103	16-pin SOP	5		10/100 Legacy			
TDK	TLA-6T103LF	16-pin SOP	5	0° - +70° C	10/100 Legacy			
Delta	LF8200M	16-pin SOP	5	+25° C	10/100 Legacy			

		LAN91C111							
	Qualified Magnetics								
Vendor	Part Number	Package	Cores	Temp	Configuration				
Pulse	J1012F21C	Integrated RJ45	4	0° - +70° C	10/100 Legacy				
Halo	TG110-S050N2	16-pin SOIC	4	0° - +70° C	HP Auto-MDIX				
		Suggested Magnetic	cs						
Bel Fuse	S558-5999-U7	16-pin SOIC	4	0° - +70° C	HP Auto-MDIX				
Bel Fuse	0810-1X1T-03	Integrated RJ45	5	0° - +70° C	10/100 Legacy				
Bel Fuse	0817-1G1T-21	Integrated RJ45	4	0° - +70° C	HP Auto-MDIX				
Pulse	H1086	16-pin SOP	5	0° - +70° C	10/100 Legacy				
Pulse	H1012	16-pin SOP	5	0° - +70° C	10/100 Legacy				
Pulse	PE-68515L	16-pin SOP	5	0° - +70° C	10/100 Legacy				
Pulse	H1089	16-pin SOP	4	0° - +70° C	10/100 Legacy				
Pulse (Valor)	ST6118T	16-pin SOP	5	0° - +70° C	10/100 Legacy				
Pulse	H1102	16-pin SOIC	4	0° - +70° C	HP Auto-MDIX				
Pulse	J1012F01C	Integrated RJ45	4	0° - +70° C	10/100 Legacy				
Halo	TG22-3506NL	16-pin SOP	5	0° - +70° C	10/100 Legacy				
Halo	TG22-3506ND	16-pin SOP	5	0° - +70° C	10/100 Legacy				
Halo	TG110-S055N2	16-pin SOIC	4	0° - +70° C	HP Auto-MDIX				
Halo	TG110-S050P1	CardBus	2	0° - +70° C	Single Channel				
Halo	TG110-S050P2	CardBus	4	0° - +70° C	HP Auto-MDIX				
Halo	TG110-S050J2	CardBus	4	0° - +70° C	HP Auto-MDIX				
Midcom	000-6241-37R	16-pin SOP	5	-40° - +85° C Note 1	10/100 Legacy				
Midcom	000-6181-37R	16-pin SOP	5	-40° - +85° C Note 1	10/100 Legacy				
Midcom	JFM24111-0101	Integrated RJ45	4	0° - +70° C	HP Auto-MDIX				
YCL	20PMT04	16-pin SOP	5	0° - +70° C	10/100 Legacy				
YCL	PH163112	16-pin SOIC	4	+25° C	HP Auto-MDIX				
PCA	EPF8033GM	16-pin SOP	5	0° - +70° C	10/100 Legacy				
PCA	EPF8143S	16-pin SOIC	4	0° - +70° C	HP Auto-MDIX				
Tamura	TTC-8139	16-pin SOIC	4	0° - +70° C	HP Auto-MDIX				

	LAN91C111I								
	Suggested Magnetics								
Vendor	Part Number	Package	Cores	Temp	Configuration				
Pulse	HX1188	16-pin SOIC	4	-40° - +85° C	HP Auto-MDIX				
Pulse	HX1198	16-pin SOIC	4	-40° - +85° C	HP Auto-MDIX				
Halo	TG110-E050N5	16-pin SOIC	4	-40° - +85° C	HP Auto-MDIX				
Halo	TG110-E055N5	16-pin SOIC	4	-40° - +85° C	HP Auto-MDIX				

	LAN91C96 @ +5V Operation						
		Suggested Magnet	ics				
Vendor	Part Number	Package	Cores	Temp	Configuration		
Bel Fuse	0556-3873-03	16-pin DIL	4	0° - +70° C	10BASE-T (LPF)		
Bel Fuse	A556-2006-00	16-pin DIL	3	0° - +70° C	10BASE-T (LPF)		
Bel Fuse	A556-2006-03	16-pin DIL	4	0° - +70° C	10BASE-T (LPF)		
Bel Fuse	A556-2006-DE	16-pin DIL	2	0° - +70° C	10BASE-T (LPF)		
Bel Fuse	S556-5999-02	16-pin SOP	4	0° - +70° C	10BASE-T (LPF)		
Bel Fuse	S556-5999-DE	16-pin SOP	2	0° - +70° C	10BASE-T (LPF)		
Bel Fuse	A553-1006-AB	16-pin DIL	3	0° - +70° C	10BASE2 & 5		
Bel Fuse	S553-1006-AE	16-pin SOIC	3	0° - +70° C	10BASE2 & 5		
Bel Fuse	S556-9003-11	PCMCIA	4	0° - +70° C	10BASE-T (LPF)		
Pulse	PE-65421	16-pin DIL	4	0° - +70° C	10BASE-T (LPF)		
Pulse	PE-68026	16-pin SOP	4	0° - +70° C	10BASE-T (LPF)		
Pulse	PE-68011	16-pin SOP	4	0° - +70° C	10BASE-T (LPF)		
Pulse	PE-68056	16-pin SOP	3	0° - +70° C	10BASE-T (LPF)		
Pulse	PE-64103	16-pin DIL	3	0° - +70° C	10BASE2		
Pulse	PE-64108	16-pin DIL	3	0° - +70° C	10BASE2 & 5		
Pulse	PE-65728	16-pin SOIC	3	0° - +70° C	10BASE2 & 5		
Pulse (Fil Mag)	78Z034C	16-pin DIL	3	0° - +70° C	10BASE-T (LPF)		
Pulse (Fil Mag)	78Z1120B-01	16-pin DIL	2	0° - +70° C	10BASE-T (LPF)		
Pulse (Fil Mag)	78Z1122B-01	16-pin DIL	4	0° - +70° C	10BASE-T (LPF)		
Pulse (Fil Mag)	23Z91SM	16-pin SOIC	3	0° - +70° C	10BASE2 & 5		
Pulse (Valor)	FL1012	16-pin DIL	3	+25° C	10BASE-T (LPF)		
Pulse (Valor)	PT3877	16-pin DIL	2	+25° C	10BASE-T (LPF)		
Halo	FD02-101G	16-pin DIL	2	0° - +70° C	10BASE-T (LPF)		
Halo	FD12-101G	16-pin DIL	3	0° - +70° C	10BASE-T (LPF)		
Halo	FD22-101G	16-pin DIL	4	0° - +70° C	10BASE-T (LPF)		
Halo	TD01-1006K	16-pin DIL	3	+25° C	10BASE2 & 5		
Halo	TD01-1006B	16-pin DIL	3	+25° C	10BASE2 & 5		
Halo	TG01-1006N	16-pin SOIC	3	+25° C	10BASE2 & 5		
Halo	TG01-1006P	PCMCIA	3	+25° C	10BASE2 & 5		

	LAN91C96 @ +5V Operation								
	Suggested Magnetics								
Vendor	Part Number	Package	Cores	Temp	Configuration				
YCL	20F001N	16-pin DIL	3	+25° C	10BASE-T (LPF)				
YCL	20F001	16-pin DIL	2	+25° C	10BASE-T (LPF)				
YCL	20LF43	16-pin SOP	4	+25° C	10BASE-T (LPF)				
YCL	20LF43S	16-pin SOP	4	+25° C	10BASE-T (LPF)				
YCL	16PT-006A	16-pin DIL	3	+25° C	10BASE2 & 5				
YCL	16PT-004A	16-pin DIL	3	+25° C	10BASE2 & 5				
YCL	16PT-006S	16-pin SOIC	3	+25° C	10BASE2 & 5				
		•							
PCA	EPE6192G	16-pin SOP	4	0° - +70° C	10BASE-T (LPF)				
PCA	EPA1885-5	16-pin SOIC	3	+25° C	10BASE2 & 5				
Tamura	TTC-8128	16-pin SOP	4	0° - +70° C	10BASE-T (LPF)				
Tamura	TTC-8121	16-pin SOIC	3	0° - +70° C	10BASE2 & 5				

LAN91C96 @ +3.3V Operation								
Qualified Magnetics								
Vendor	Part Number	Package	Cores	Temp	Configuration			
Pulse	PE-68056	16-pin SOP	3	0° - +70° C	10BASE-T (LPF)			

	LAN91C96I @ +5V Operation								
	Suggested Magnetics								
Vendor	Vendor Part Number Package Cores Temp Configura								
Bel Fuse	A556-2006-02	16-pin DIL	4	-40° - +85° C	10BASE-T (LPF)				
Pulse	EX2001	16-pin SOP	4	-40° - +85° C	10BASE-T (LPF)				

Note 1: The LAN83C185, LAN9115, LAN9116, LAN9117, LAN9118, LAN91C111, LAN8187, LAN8700, LAN9210, LAN9211, LAN9215, LAN9217, LAN9218, LAN9131, LAN9132, LAN9311, LAN9312, LAN9313, LAN9420, LAN9500 are rated for the Commercial Temperature (0° - +70° C) range only.

APPENDIX A: APPLICATION NOTE REVISION HISTORY

TABLE A-1: REVISION HISTORY

Revision Level & Date	Section/Figure/Entry	Correction
DS00003016A (03-22-19)	Replaces previous SMSC version Rev. 3.1 (06-27-11)	
Rev. 3.1 (06-27-11)	Third Table	Removed LAN8810 & LAN8820 from table heading. Heading is now "LAN7500".
	Fourth Table	Removed LAN8820i from table heading. Heading is now "LAN8810i, LAN7500i".
	Fifth Table	Removed LAN88710 from table heading. Heading is now "LAN89218, LAN89303".
Rev. 3.0 (03-15-10)	First Table	Added LAN9303, LAN9303M, LAN9500A, LAN9513
	Second Table	Added LAN9303i, LAN9303Mi, LAN9500Ai, LAN9513i
	Third Table	Added new table for LAN8810, LAN8820, LAN7500 with Halo magnetics
	Fourth Table	Added new table for LAN8810i, LAN8820i, LAN7500i with Halo magnetics
	Fifth Table	Moved down to accommodate new tables, added LAN88710, LAN89303, and new Halo magnetic
Rev. 2.97 (08-21-09)	First Table	Added LAN9512, LAN9514, LAN8710, LAN8720
	Second Table	Added LAN8710i, LAN8720i
	Third Table	Added new table for LAN89218 with Halo magnetics

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our
 knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data
 Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, AnyRate, AVR, AVR logo, AVR Freaks, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, Heldo, JukeBlox, KeeLoq, Kleer, LANCheck, LINK MD, maXStylus, maXTouch, MediaLB, megaAVR, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, Prochip Designer, QTouch, SAM-BA, SpyNIC, SST, SST Logo, SuperFlash, tinyAVR, UNI/O, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

ClockWorks, The Embedded Control Solutions Company, EtherSynch, Hyper Speed Control, HyperLight Load, IntelliMOS, mTouch, Precision Edge, and Quiet-Wire are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, Anyln, AnyOut, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KleerNet, KleerNet logo, memBrain, Mindi, MiWi, motorBench, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2009-2019, Microchip Technology Incorporated, All Rights Reserved.

ISBN: 9781522443049

QUALITY MANAGEMENT SYSTEM CERTIFIED BY DNV = ISO/TS 16949=

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



Worldwide Sales and Service

AMERICAS

Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200

Fax: 480-792-7277 Technical Support:

http://www.microchip.com/

support Web Address:

www.microchip.com

Atlanta Duluth, GA

Tel: 678-957-9614 Fax: 678-957-1455

Austin, TX Tel: 512-257-3370

Boston

Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088

Chicago Itasca, IL

Tel: 630-285-0071 Fax: 630-285-0075

Dallas

Addison, TX Tel: 972-818-7423 Fax: 972-818-2924

Detroit Novi, MI

Tel: 248-848-4000

Houston, TX

Tel: 281-894-5983 Indianapolis

Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380

Los Angeles

Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800

Raleigh, NC Tel: 919-844-7510

New York, NY Tel: 631-435-6000

San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270

Canada - Toronto Tel: 905-695-1980 Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney Tel: 61-2-9868-6733

China - Beijing Tel: 86-10-8569-7000

China - Chengdu Tel: 86-28-8665-5511

China - Chongqing Tel: 86-23-8980-9588

China - Dongguan Tel: 86-769-8702-9880

China - Guangzhou Tel: 86-20-8755-8029

China - Hangzhou Tel: 86-571-8792-8115

China - Hong Kong SAR Tel: 852-2943-5100

China - Nanjing Tel: 86-25-8473-2460

China - Qingdao Tel: 86-532-8502-7355

China - Shanghai Tel: 86-21-3326-8000

China - Shenyang Tel: 86-24-2334-2829

China - Shenzhen Tel: 86-755-8864-2200

China - Suzhou Tel: 86-186-6233-1526

China - Wuhan Tel: 86-27-5980-5300

China - Xian Tel: 86-29-8833-7252

China - Xiamen
Tel: 86-592-2388138

China - Zhuhai Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore Tel: 91-80-3090-4444

India - New Delhi Tel: 91-11-4160-8631

India - Pune Tel: 91-20-4121-0141

Japan - Osaka Tel: 81-6-6152-7160

Japan - Tokyo Tel: 81-3-6880- 3770

Korea - Daegu

Tel: 82-53-744-4301 **Korea - Seoul** Tel: 82-2-554-7200

Malaysia - Kuala Lumpur Tel: 60-3-7651-7906

Malaysia - Penang Tel: 60-4-227-8870

Philippines - Manila Tel: 63-2-634-9065

Singapore Tel: 65-6334-8870

Taiwan - Hsin Chu Tel: 886-3-577-8366

Taiwan - Kaohsiung Tel: 886-7-213-7830

Taiwan - Taipei Tel: 886-2-2508-8600

Thailand - Bangkok Tel: 66-2-694-1351

Vietnam - Ho Chi Minh Tel: 84-28-5448-2100

EUROPE

Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393

Denmark - Copenhagen Tel: 45-4450-2828 Fax: 45-4485-2829

Finland - Espoo Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching Tel: 49-8931-9700

Germany - Haan Tel: 49-2129-3766400

Germany - Heilbronn Tel: 49-7131-67-3636

Germany - Karlsruhe Tel: 49-721-625370

Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44

Germany - Rosenheim Tel: 49-8031-354-560

Israel - Ra'anana Tel: 972-9-744-7705

Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781

Italy - Padova Tel: 39-049-7625286

Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340

Norway - Trondheim Tel: 47-7288-4388

Poland - Warsaw Tel: 48-22-3325737

Romania - Bucharest Tel: 40-21-407-87-50

Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91

Sweden - Gothenberg Tel: 46-31-704-60-40

Sweden - Stockholm Tel: 46-8-5090-4654

UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820