



				single-shift approx
	hanning	hamming		hanning
0	0.0102	0.08	>>6	0.015625
1	0.0405	0.0894	>>5	0.03125
2	0.0896	0.1172	>>4	0.0625
3	0.1555	0.1624	>>3	0.125
4	0.2355	0.223	>>2	0.25
5	0.3263	0.2966	>>1	0.5
6	0.4242	0.3802	>>1	0.5
7	0.5253	0.4703	>>1	0.5
8	0.6253	0.5632	>>1	0.5
9	0.7201	0.6553	>>0	1
10	0.806	0.7425	>>0	1
11	0.8793	0.8215	>>0	1
12	0.9371	0.889	>>0	1
13	0.97706	0.9421	>>0	1
14	0.9974	0.9789	>>0	1
15	0.9974	0.9976	>>0	1