


Calibration checkerboard: 9x6 inner corners, 25 mm squares



Tape flat to something rigid (a clipboard or a book). Check one square = 25 mm.

this bar must measure exactly 100 mm; if not, reprint at 100% / Actual size

