INTERNAL TROUBLE REPORT

ITR NO: 000085

Inspection Date Station 05-02-2013 Test

Part No. Operator 1056981 Tester 2

Plant

David City

Defect Type

Inspector: Tester 1 Defect Qty

00 5

Inspection Summary

Test Summary for May 2

Discrepancies

Discrepancies for May 2

Interim Containment

Interim Containment

Root Cause

Root Cause

Corrective Action/Preventive Action

Corrective Action

Result of Preventive Action

Result of Preventive Action

Material Costs

Part Number Cost Quantity Total Cost Manufacturing Minutes Rework Cost TCA12345 5.15 7 36.05 90 27.00

Reviewed By

Department Manager: Tester Date: 05-02-2013
QA Department Head: Tester Date: 05-02-2013