

## Cathode Design

Thursday, April 27, 2017


7:10 PM





## Tapared Cathodes

The issue with an insulated AND tapered cathode is that it machines a hole of A's diameter, but the tool will soon collide with the part.




K-A->|
The hole will never be large enough for point A NOT to collide with


Point b


A tapered cathode can only be used without insulation, and can only make a cut like the one below



Tailored Cathodes - can be used to make a radially symmetric part easily.







This type of cathode leaves an imprint in the Workpiece. The cathode is only good for one type of part.