

Mode 3 — Square-BFP (centered / opt)

DP8 (16×8) → DP8 (16×4) → DP8 (8×4) → block exponents → DP8 (4×4) → centered add-and-square

Step 1 — DP8 (16×8)

$$\text{DP8 } (16 \times 8) = \sum_{i=0}^7 a_i b_i$$

Step 2 — DP8 (16×4)

$$\text{DP8 } (16 \times 8) = \underbrace{2^4 \sum_{i=0}^7 a_i b_i^{hi}}_{\text{DP8 } (16 \times 4)} + \underbrace{\sum_{i=0}^7 a_i b_i^{lo}}_{\text{DP8 } (16 \times 4)}$$

Step 3 — DP8 (8×4)

$$\text{DP8 } (16 \times 8) = 2^{12} \underbrace{\sum_{i=0}^7 a_i^{hi} b_i^{hi}}_{\text{DP8 } (8 \times 4)} + 2^8 \underbrace{\sum_{i=0}^7 a_i^{hi} b_i^{lo}}_{\text{DP8 } (8 \times 4)} + 2^4 \underbrace{\sum_{i=0}^7 a_i^{lo} b_i^{hi}}_{\text{DP8 } (8 \times 4)} + \underbrace{\sum_{i=0}^7 a_i^{lo} b_i^{lo}}_{\text{DP8 } (8 \times 4)}$$

Step 4 — Block exponents (one exponent block per DP8 (8×4) — all copies of one E)

$$(P_j, E) \text{ per DP8 } (8 \times 4) \text{ above,} \quad E = E_a + E_b \longrightarrow (M, E)$$

$\delta \equiv 0$: M is the Step-3 sum unchanged; $\text{DP8 } (16 \times 8) = M \cdot 2^E$.

Step 5 — DP8 (4×4)

$$\begin{aligned} M = & 2^{16} \underbrace{\sum_{i=0}^7 a_{H,i}^{hi} b_i^{hi}}_{\text{DP8 } (4 \times 4)} + 2^{12} \underbrace{\sum_{i=0}^7 a_{L,i}^{hi} b_i^{hi}}_{\text{DP8 } (4 \times 4)} + 2^{12} \underbrace{\sum_{i=0}^7 a_{H,i}^{hi} b_i^{lo}}_{\text{DP8 } (4 \times 4)} + 2^8 \underbrace{\sum_{i=0}^7 a_{L,i}^{hi} b_i^{lo}}_{\text{DP8 } (4 \times 4)} \\ & + 2^8 \underbrace{\sum_{i=0}^7 a_{H,i}^{lo} b_i^{hi}}_{\text{DP8 } (4 \times 4)} + 2^4 \underbrace{\sum_{i=0}^7 a_{L,i}^{lo} b_i^{hi}}_{\text{DP8 } (4 \times 4)} + 2^4 \underbrace{\sum_{i=0}^7 a_{H,i}^{lo} b_i^{lo}}_{\text{DP8 } (4 \times 4)} + \underbrace{\sum_{i=0}^7 a_{L,i}^{lo} b_i^{lo}}_{\text{DP8 } (4 \times 4)} \end{aligned}$$

Step 6 — Centered add-and-square (subtract 8 from unsigned nibbles $a_L^{hi}, a_H^{lo}, a_L^{lo}, b^{lo}$; per DP8 (4×4) add $c = 0/512/2048$ for 0/1/2 unsigned nibbles)

$$\begin{aligned} M = & 2^{16} \frac{1}{2} \underbrace{\left(\sum_{i=0}^7 (a_{H,i}^{hi} + b_i^{hi})^2 - \sum_{i=0}^7 (a_{H,i}^{hi})^2 - \sum_{i=0}^7 (b_i^{hi})^2 \right)}_{\text{DP8 } (4 \times 4)} \\ & + 2^{12} \frac{1}{2} \underbrace{\left(\sum_{i=0}^7 ((a_{L,i}^{hi} - 8) + b_i^{hi})^2 - \sum_{i=0}^7 (a_{L,i}^{hi} - 8)^2 - \sum_{i=0}^7 (b_i^{hi} - 8)^2 + 512 \right)}_{\text{DP8 } (4 \times 4)} \\ & + 2^{12} \frac{1}{2} \underbrace{\left(\sum_{i=0}^7 (a_{H,i}^{hi} + (b_i^{lo} - 8))^2 - \sum_{i=0}^7 (a_{H,i}^{hi} - 8)^2 - \sum_{i=0}^7 (b_i^{lo} - 8)^2 + 512 \right)}_{\text{DP8 } (4 \times 4)} \\ & + 2^8 \frac{1}{2} \underbrace{\left(\sum_{i=0}^7 ((a_{L,i}^{lo} - 8) + (b_i^{lo} - 8))^2 - \sum_{i=0}^7 (a_{L,i}^{lo} - 16)^2 - \sum_{i=0}^7 (b_i^{lo} - 16)^2 + 2048 \right)}_{\text{DP8 } (4 \times 4)} \\ & + 2^8 \frac{1}{2} \underbrace{\left(\sum_{i=0}^7 ((a_{H,i}^{lo} - 8) + b_i^{hi})^2 - \sum_{i=0}^7 (a_{H,i}^{lo} - 8)^2 - \sum_{i=0}^7 (b_i^{hi} - 8)^2 + 512 \right)}_{\text{DP8 } (4 \times 4)} \\ & + 2^4 \frac{1}{2} \underbrace{\left(\sum_{i=0}^7 ((a_{L,i}^{lo} - 8) + b_i^{hi})^2 - \sum_{i=0}^7 (a_{L,i}^{lo} - 8)^2 - \sum_{i=0}^7 (b_i^{hi} - 8)^2 + 512 \right)}_{\text{DP8 } (4 \times 4)} \end{aligned}$$

$$\begin{aligned}
& + 2^4 \underbrace{\frac{1}{2} \left(\sum_{i=0}^7 ((a_{H,i}^{lo} - 8) + (b_i^{lo} - 8))^2 - \sum_{i=0}^7 (a_{H,i}^{lo} - 16)^2 - \sum_{i=0}^7 (b_i^{lo} - 16)^2 + 2048 \right)}_{\text{DP8 (4}\times\text{4)}} \\
& + \frac{1}{2} \underbrace{\left(\sum_{i=0}^7 ((a_{L,i}^{lo} - 8) + (b_i^{lo} - 8))^2 - \sum_{i=0}^7 (a_{L,i}^{lo} - 16)^2 - \sum_{i=0}^7 (b_i^{lo} - 16)^2 + 2048 \right)}_{\text{DP8 (4}\times\text{4)}}
\end{aligned}$$

Step 7 — All components

$$\begin{aligned}
\text{PE} &= 2^{16} \sum_{i=0}^7 (a_{H,i}^{hi} + b_i^{hi})^2 + 2^{12} \sum_{i=0}^7 ((a_{L,i}^{hi} - 8) + b_i^{hi})^2 + 2^{12} \sum_{i=0}^7 (a_{H,i}^{hi} + (b_i^{lo} - 8))^2 + 2^8 \sum_{i=0}^7 ((a_{L,i}^{hi} - 8) + (b_i^{lo} - 8))^2 \\
&+ 2^8 \sum_{i=0}^7 ((a_{H,i}^{lo} - 8) + b_i^{hi})^2 + 2^4 \sum_{i=0}^7 ((a_{L,i}^{lo} - 8) + b_i^{hi})^2 + 2^4 \sum_{i=0}^7 ((a_{H,i}^{lo} - 8) + (b_i^{lo} - 8))^2 + \sum_{i=0}^7 ((a_{L,i}^{lo} - 8) + (b_i^{lo} - 8))^2 \\
\alpha &= 2^{16} \sum_{i=0}^7 (a_{H,i}^{hi})^2 + 2^{12} \sum_{i=0}^7 (a_{L,i}^{hi} - 8)^2 + 2^{12} \sum_{i=0}^7 (a_{H,i}^{hi} - 8)^2 + 2^8 \sum_{i=0}^7 (a_{L,i}^{hi} - 16)^2 \\
&+ 2^8 \sum_{i=0}^7 (a_{H,i}^{lo} - 8)^2 + 2^4 \sum_{i=0}^7 (a_{L,i}^{lo} - 8)^2 + 2^4 \sum_{i=0}^7 (a_{H,i}^{lo} - 16)^2 + \sum_{i=0}^7 (a_{L,i}^{lo} - 16)^2 \\
\beta &= 2^{16} \sum_{i=0}^7 (b_i^{hi})^2 + 2^{12} \sum_{i=0}^7 (b_i^{hi} - 8)^2 + 2^{12} \sum_{i=0}^7 (b_i^{lo} - 8)^2 + 2^8 \sum_{i=0}^7 (b_i^{lo} - 16)^2 \\
&+ 2^8 \sum_{i=0}^7 (b_i^{hi} - 8)^2 + 2^4 \sum_{i=0}^7 (b_i^{hi} - 8)^2 + 2^4 \sum_{i=0}^7 (b_i^{lo} - 16)^2 + \sum_{i=0}^7 (b_i^{lo} - 16)^2 \\
C &= 0 + 2097152 + 2097152 + 524288 + 131072 + 8192 + 32768 + 2048 = 4892672 \\
M &= \frac{1}{2} (\text{PE} - \alpha - \beta + C), \quad E = E_a + E_b
\end{aligned}$$