

▲ Fields

beginningTimeInUse : double

endingTimeInUse : double

currentPart : Part

errorProbability : int

machineType : string

metalRemovalRate : double

getCalcMachineTime() : double

getInfluenceOnQuality() : double

getCurrentPart() : Part

getEndTime() : double

getInRepair() : bool

possibleError() : bool

getMachineType(): string

setCurrentPart(Part P) : void

setInRepair(bool b) : void

setInUse(bool B) : void

setMachinedVolume(): void

DoString(): string

getInUse() : bool

prepair(): void

addToEndingTime(int endTime) : void

inRepair : bool

machineID: int

wear : double

■ Methods

xCoordinate : int

yCoordinate : int

inUse : bool















